

Manual

Mini inverter welder

60%
Duty cycle

Applies for:

Code	Model
29017	SOIN-310MP



CAUTION



Read this manual thoroughly
before using the tool.



Technical data	3
Electrical requirements	3
 General safety requirements for electric tools.....	4
 Safety warnings for the use of mini inverter welders.....	5
Parts	6
Installation (SMAW)	7
Start up	8
Maintenance	10
Symbols	10
Troubleshooting	11
Notes	12
Authorized service centers	13
Warranty policy	14

⚠ CAUTION

To get the most out of the tool, extend its lifespan, claim the warranty if necessary, and avoid serious risks or injuries, please read this manual thoroughly before using the tool.

Please keep this manual for future references.

The illustrations in this manual are for reference only and may differ from the real appearance of the tool.

Use and care recommendations

 **RESPECT THE DUTY CYCLES**
6 minutes work per 4 minutes rest

 **OUTPUT CURRENT RANGE:**
Connected to 127 V ~ 20 A - 100 A

 **COATED ELECTRODE DIAMETERS:**
Process SMAW 6013-6011 (3/32", 1/8") | 7018 (3/32")



THERMAL PROTECT The machine is equipped with a THERMAL PROTECTOR that, in case of overheating, turns off the welder and activates the thermal protection LED light. If this occurs, allow the welder to cool for 15 minutes and then restart it.

 It is recommended to use a **14 AWG** gauge extension cord and connect to an **INDEPENDENT POWER SOURCE**.

 Perform regular **MAINTENANCE** on your machine (page 10).

SOIN-310MP

Code •	29017		
Description •	Mini inverter welder		
Input voltage •	127 V~		
Frequency •	50 Hz / 60 Hz		
Rated input capacity •	3.5 kVA		
Open-circuit voltage •	82 V c.c.		
Power factor •	0.82		
Current range •	20 A - 100 A		
Nominal duty cycle •	60% 6 minutes of work per 4 minutes of rest. The specified output values are given at a temperature of 68 °F. At higher temperatures, the duty cycle may be reduced.		
Electrode diameter (SMAW) •	3/32" - 1/8"		
Measurements •	3.9" x 9.5" x 5.9"	Weight •	5.3 lb
Insulation •	Class I	Grade IP •	IP21S
Conductors •	14 AWG x 3C with an insulating temperature of 221 °F		

The power cable has cable ties type: Y The construction class of the tool is: Basic insulation
The thermal insulation class of the windings: Class H

⚠ WARNING If the power cable is damaged, it must be replaced by the manufacturer or an Authorized TRUPER Service Center to prevent any risk of electric shock or significant accidents. The electrical insulation of this tool is altered by splashes or spillage of liquids during its operation. Do not expose it to rain, liquids, and/or moisture.



⚠ WARNING Before accessing the terminals, all power circuits must be disconnected.




Electrical requirements

⚠ WARNING In the event of faults or malfunctions, grounding provides a path with minimal resistance for electrical current, reducing the risk of electric shock. This tool is equipped with an electrical cable that has a grounding conductor and a plug with a ground connection. The plug must be connected to an outlet that is installed and grounded in accordance with all local codes.



⚠ WARNING Do not modify the provided plug. If the plug does not fit the outlet, obtain the appropriate outlet installed by a qualified electrician.



- If using the welder alongside other tools with the same ground, connect them in parallel, never in series.

⚠ CAUTION • The gauge of the grounding conductor cannot be smaller than the power supply cable.

⚠ CAUTION • The connection to the power source must be carried out by a professional electrician.

⚠ CAUTION • Always confirm that the input connection voltage, as stated on the welder's information plate, matches the voltage of the power supply.

⚠ CAUTION • The gauge of the power supply cable must meet the following requirements:



Switch	≥ 30 A
Fuse (Nominal working current)	30 A (*)
Electrical wire	≥ 2.5 mm ²

* The fuse's melting current is twice its nominal current.

- If extensions are needed between the welder and the workpiece, increase the gauge of the welding cable to maintain the welder's power output with a potential drop not exceeding 4 V.

⚠ WARNING. Read all safety warnings and all instructions listed below carefully. Failure to follow any of them may result in electric shock, fire, and/or serious injury. Keep the warnings and instructions for future reference.

Work area**Keep your work area clean, organized, and well-lit.**

Cluttered and dim areas can lead to accidents.

**Do not operate the tool in explosive atmospheres, such as in the presence of flammable liquids, gas, or dust.**

The electric tools produce sparks that can ignite flammable material.

**Keep children and other individuals at a safe distance while using the equipment.**

Distractions can cause loss of control and lead to accidents.

Electrical safety**Electrical tool plugs must match the outlet. Never modify the plug in any way. Do not use adapters with grounded electrical tools.**

Unmodified electrical tools and matching plugs will reduce the risk of electric shock.

**Avoid bodily contact with grounded surfaces, such as pipes, radiators, stoves, and refrigerators.**

There is an increased risk of electric shock if your body is grounded.

Do not expose the tool to rain or humid conditions.

Water entering the tool increases the risk of electric shock.

Do not force the cable. Never use the cable for carrying, lifting, or disconnecting the tool. Keep the cable away from heat, oil, sharp edges, or moving parts.

Damaged or tangled cables increase the risk of electric shock.

When operating an electrical tool outdoors, use an extension cord suitable for outdoor use.

The use of a suitable outdoor-rated cable reduces the risk of electric shock.

If it is unavoidable to operate an electrical tool in a damp location, use a power source protected by a Residual Current Device (RCD).

The use of a Residual Current Device (RCD) reduces the risk of electric shock.

Personal safety**Be alert, watch what you are doing, and use common sense when handling a tool. Do not use it if you are tired or under the influence of drugs, alcohol, or medication.**

A moment of distraction while using the tool can cause personal injury.

Use safety equipment. Always wear eye protection.

The use of safety equipment such as safety glasses, dust mask, slip-resistant shoes, helmet, and ear protection in appropriate conditions significantly reduces the risk of personal injury.

**Avoid accidental starts. Ensure the switch is in the "off" position before connecting to the power source and/or the battery or transporting the tool.**

Carrying power tools with your finger on the switch or connecting power tools with the switch in the "on" position can cause accidents.

Remove any wrenches or adjusting tools before starting the power tool.

Wrenches or tools left on the rotating parts of the tool can cause personal injury.

Do not exceed your range of motion. Keep both feet firmly planted on the ground and always maintain balance.

This allows better control of the tool in unexpected situations.

**Dress appropriately. Do not wear loose clothing or jewelry. Keep your hair, clothing, and gloves away from moving parts.**

Loose clothes, jewelry, or long hair can get caught in moving parts.

If dust extraction and collection devices are available for the tool, check their connections and use them correctly.

The use of these devices reduces risks associated with dust.

Tool use and care**Do not force the tool.****Use the appropriate tool for the task at hand.**

The right tool performs better and is safer when used at the intended pace.

Do not use the tool if the switch is not functioning.

Any power tool that cannot be turned on or off is dangerous and must be repaired before operation.

Disconnect the tool from the power source and/or battery before making any adjustments, changing accessories, or storing it.

These measures reduce the risk of accidentally starting the tool.

**Store the tools out of the reach of children and do not allow them to be handled by individuals unfamiliar with the tools or their instructions.**

Power tools are dangerous in untrained hands.

**Maintain the tool. Ensure that the moving parts are not misaligned or jammed, and that there are no broken parts or other conditions that may affect its operation. Repair any damage before using the tool.**

Many accidents are caused by inadequate tool maintenance.

Keep cutting accessories sharp and clean.

Well-maintained cutting accessories are less likely to jam and easier to control.

Use the tool, its components, and accessories in accordance with these instructions and as intended for the type of tool, in appropriate working conditions.

Using the tool for applications other than those for which it is designed could cause a hazardous situation.

Service**Repair the tool at an Authorized TRUPER Service Center using only identical replacement parts**

to maintain the safety of the tool.



This tool is in compliance with the Official Mexican Standard (NOM - Norma Oficial Mexicana).

Safety warnings

⚠ for the use of mini inverter welders ⚠

PRETUL

Welding protection equipment

⚠ WARNING • Use a welding mask; it will protect your eyes and face while working with the welder.

Ensure that the shade lens of the mask is suitable for the welding process at hand.

⚠ CAUTION • Wear special welding gloves, as well as leather aprons and gaiters.

• Use sturdy, long-sleeved clothing made of flame-resistant materials such as wool or leather.

• Employ special screens or curtains to isolate the work area from pedestrian traffic and protect them from sparks, flashes, and slag produced by the welding process.

• Workbenches and tables where workpieces are placed should have holes or slots that allow for easy passage of residues generated by the welding process.

To prevent electric shocks

⚠ CAUTION • Ensure a secure connection of input and output cables, with proper insulation and intact connections (check and eliminate any possibility of a short circuit).

⚠ CAUTION • Confirm that the welder has a reliable ground connection.

⚠ CAUTION • Do not expose the welder to rain or humid conditions.

⚠ CAUTION • Stay insulated from the workpiece and ground by standing on dry, insulating mats.

⚠ DANGER • Under no circumstances touch both poles of the welder circuit (rod and workpiece).

⚠ WARNING • Do not attempt to adjust the welder's current while performing welding work.

⚠ CAUTION • Connect the ground clamp to the workpiece as close to the welding zone as possible to prevent current from flowing over long distances and eliminate the possibility of a short circuit.

⚠ WARNING • The workpiece must contact the grounding clamp before operating the welder and should not be disconnected until welding is complete, as it can lead to severe shocks and injuries.

⚠ WARNING • Disconnect the welder from the power source before performing maintenance.

To prevent fires

⚠ CAUTION • Always have a well-maintained fire extinguisher nearby.

⚠ WARNING • There should be no flammable or explosive materials in the work area (at least 36' away). Do not weld in locations where sparks can reach or fall onto flammable or explosive materials.

To avoid health risks

⚠ WARNING • Vapors and gases produced during welding work are hazardous to health. Work in well-ventilated areas or with appropriate ventilation systems.

⚠ WARNING • Do not breathe the fumes and gases from the welding process; keep your head away from the emissions.

⚠ DANGER • If ventilation is poor, use a suitable self-contained respirator, as welding-generated shielding gases can displace air and cause a fatal accident.

⚠ CAUTION • Do not operate the welder near degreasers, cleaners, or spray containers, as the heat and radiation from the welding process can react with vapors, forming toxic gases.

⚠ CAUTION • Avoid welding on metals coated with lead, zinc, or cadmium, as they produce toxic gases. Otherwise, remove the coating from the welding area, ensure the area is well-ventilated, or use a suitable self-contained respirator.

To prevent injuries and accidents

⚠ WARNING • Electric shock risk:

Electric shock from the welding electrode can be fatal. Do not weld in the rain or snow. Do not touch the electrode with bare hands. Do not use wet or damaged gloves. Protect against electric shock: isolate from the workpiece. Do not open the equipment enclosure. Do not weld on drums or any closed container.

⚠ WARNING • Welding sparks can cause explosion or fire.



⚠ WARNING • Arc-related risk:

Arc radiation can burn the eyes and damage the skin. Use a welding mask and protective glasses. Use ear protection and protective clothing covering the skin up to the neck. Use full-body protection.



⚠ WARNING • Risk induced by electromagnetic fields:

Welding current produces an electromagnetic field.



Do not use the equipment with medical implants. Never coil welding cables around the body. Place the two welding cables together and parallel so that their fields counteract each other.

⚠ WARNING • Do not use the welding power source to thaw pipes.

⚠ CAUTION • Never allow inexperienced individuals to disassemble or adjust the welding apparatus.

⚠ WARNING • Ensure both the operator and the welder are out of the path of falling sparks and residues from the welding process.


• Operate the welder in a protected area away from direct sunlight and rain, free from violent vibrations.

• Store the welder in a dry place with a temperature range of -13 °F to 131 °F

• Maintain a 11.8" space around the welder for proper ventilation.

⚠ CAUTION • Ensure no foreign metal objects are inside the welder.

⚠ WARNING • Any issues with the welder that cannot be resolved by the operator adjusting for proper welding must be addressed at an Authorized TRUPER Service Center. Never attempt to open the welder cover for any maintenance.



Connections

CAUTION To prevent electric shocks, it is necessary to refer to the information in the "Electrical requirements" section on page 3.

- The quick connections of the electrode holder and the grounding clamp are inserted and turned a quarter of a turn clockwise into the front panel outlets to ensure a secure fit.

Reverse polarity (A)

- Connect the grounding clamp cable to the negative (-) output terminal of the welder.
- Connect the grounding clamp (**C**) to the workpiece.
- Connect the electrode holder cable to the positive (+) output terminal of the welder.

This configuration generates more heat in the electrode, providing greater penetration with basic electrodes, making it ideal for welding thick pieces.



Direct polarity (B)

- Connect the grounding clamp cable to the positive (+) output.
- Connect the grounding clamp (**C**) to the workpiece.
- Connect the electrode holder cable to the negative (-) output.

This configuration generates more heat in the workpiece, resulting in less deformation and narrower beads, making it ideal for welding thin pieces.


- Connect the power cable (**D**) to the power supply at the corresponding voltage (127 V~).

WARNING Before using the welder, it must be properly grounded. Do not uninstall the grounding cable, as doing so may lead to serious bodily injuries.




Preparations

- A quality welding work can only be ensured by experience, practice, and attention to detail.
- Numerous factors come into play in the welding process: required current, distance between the electrode and the workpiece, welding speed and direction, thickness and type of material, workpiece position, electrode angle, as well as the gauge, material, and coating of the electrode. Therefore, it is advisable to practice on scrap material before undertaking actual welding to determine the specific requirements of the job.
- The area of the workpieces where welding will be applied must be clean, free of rust, and paint.
- Joints between sheets with gauges exceeding $1/8"$ (3 mm) should be beveled for proper welding (A).



Welding

- Set the switch (B) to the ON (I) position.
- Adjust the current control knob (C) to achieve the appropriate current and arc intensity for the job.
- Hold the electrode holder in the most comfortable manner possible. Keep in mind that during the welding process, the angle, movement, and distance from the workpiece should be constant and uniform.
- Direct the electrode tip toward the joint to be welded to generate the electric arc and start welding.
- Begin welding once the arc ignites, always keeping the electrode tip approximately $0.08"$ away from the workpiece. If you weld with the electrode resting on the workpiece, it may stick, resulting in poor-quality welding.



Overload

Overloads can occur in the event of a failure in the power system or inside the welder. If this happens, and the indicator lights up (D), turn off the welder, check for external causes, and address the problem. If none is found, turn off the power switch and turn it back on. If the overload light does not disappear after turning the power switch off and on, contact an Authorized TRUPER Service Center.

Slag removal


- After completing the welding job, use the included wire brush to remove slag from the surface of the weld bead.
- CAUTION** • Wait for the slag to cool and harden before removing it.
- Particles may be expelled when striking or brushing the slag. Use eye protection and keep people at a distance.



Electrode replacement

- When the electrode has been consumed 0.4" to 0.8" from the electrode holder, it is necessary to replace it with a new one to continue welding.
- CAUTION** • The electrode burns at a high temperature. Do not attempt to handle electrode remnants with your hands. Place the remnants in a metal container.
- Open the electrode holder clamp to hold the new electrode by the uncoated end. Do not hold the electrode by the coated part.

Examples of welding



- Proper usage and regular cleaning extend the lifespan of the welder.

CAUTION • Only qualified personnel should perform repairs. It is recommended to visit an Authorized TRUPER Service Center for welding machine repairs and to purchase supplies or accessories.

Regular maintenance

- A service technician should use compressed air to clean the welder of dust. If there is a significant amount of dust, immediate cleaning is necessary. Under normal conditions, cleaning is required once a year. If the welder is exposed to a lot of dust, cleaning should be done every three months.
- During cleaning, check for any loose parts or components in the welder.
- Keep the welder's cable plug in good condition.
- The plug should be checked before each use.

Storage

- If the welder is going to be stored for an extended period, it should be kept in a dry and well-ventilated area to prevent moisture, rust, or toxic gases. The storage temperature ranges from -13 °F to 131 °F, and the relative humidity should not exceed 90%.

Symbols

	Direct current
	Manual arc welding with coated electrode
	Metal inert gas welding and active gas welding, including the use of flux-cored wire
	Input circuit, symbol for single-phase alternating current, and nominal frequency
x	Duty cycle symbol (service factor)
I_2	Symbol for nominal welding current
U_2	Symbol for conventional load voltage
$U_0 \dots V$	Nominal open-circuit voltage
$U_1 \dots V$	Nominal supply voltage
$I_{1\max} \dots A$	Maximum nominal feeding current
$I_{1\text{eff}} \dots A$	Maximum effective feeding current
IP	Degree of protection (solid objects and water ingress)
	Converter - transformer - single- phase static frequency rectifier
	Symbol for alternating current
SMAW	Manual arc welding with coated electrodes
TIG	Gas-shielded arc welding system
MIG	Metal inert gas welding
	Tungsten inert gas welding

Problem	Cause	Corrective action
The thermal protection light is on.	<ul style="list-style-type: none">Inadequate ventilation for the welder.Very high ambient temperature.The welder was used for a longer time than recommended in its duty cycle.	<ul style="list-style-type: none">Keep the welder away from any wall at least 11.8" to allow air circulation.The welder will recover once the temperature returns to the appropriate operating range.The welder will recover once the temperature returns to the appropriate operating range.
The current adjustment control does not work.	<ul style="list-style-type: none">The potentiometer is broken.	<ul style="list-style-type: none">Visit an Authorized TRUPER Service Center to replace the potentiometer.
The fan is not working or rotating very slowly.	<ul style="list-style-type: none">Malfunctioning switch.Malfunctioning fan.Connection failure.	<ul style="list-style-type: none">Visit an Authorized TRUPER Service Center to replace the switch.Visit an Authorized TRUPER Service Center to repair the fan.Check the connections.
No open-circuit voltage.	<ul style="list-style-type: none">High voltage, low voltage, or a missing phase.The welder is overheating.Malfunctioning switch.	<ul style="list-style-type: none">The welder will recover once the temperature returns to the appropriate operating range.Visit an Authorized TRUPER Service Center to replace the switch.
The electrode holder gets too hot; the + and - connections heat up.	<ul style="list-style-type: none">The electrode holder capacity is too low.The cable size is too small.Loose connections.Increased resistance between the electrode holder and the cable.	<ul style="list-style-type: none">Replace the electrode holder with one of higher capacity.Replace the cable with one within the requirements (refer to page 3).Clean rust accumulation and tighten connections.Clean rust accumulation and tighten connections.
Power source is cut off.	<ul style="list-style-type: none">The welder has overheated.	<ul style="list-style-type: none">No malfunction. It is normal for the power supply to be cut off when the welder exceeds its normal working temperature. Wait for the temperature to return to the appropriate working range before turning it on again.
Large spark.	<ul style="list-style-type: none">Incorrect output polarity connection.	<ul style="list-style-type: none">Change the output line.

If problems persist despite taking the recommended corrective actions,
contact an Authorized TRUPER Service Center.

In the event of any problem contacting an Authorized Truper Service Center, please see our webpage WWW.TRUPER.COM to get an updated list, or call our toll-free numbers **800 690-6990** or **800 018 7873** to get information about the nearest Service Center.

AGUASCALIENTES DE TODO PARA LA CONSTRUCCIÓN

GRAL. BARRAGÁN #1201, COL. GREMIAL, C.P. 20030,
AGUASCALIENTES, AGS. TEL.: 449 994 0537

BAJA CALIFORNIA SUCURSAL TIJUANA

AV. LA ENCANTADA, LOTE #5, PARQUE INDUSTRIAL EL
FLORIDO II, C.P. 22244, TIJUANA, B.C.
TEL.: 664 969 5100

BAJA CALIFORNIA SUR FIX FERRETERÍAS

FELIPE ÁNGELES ESQ. RUIZ CORTÍNEZ S/N, COL. PUEBLO
NUEVO, C.P. 23670, CD. CONSTITUCIÓN, B.C.S.
TEL.: 613 132 1115

CAMPECHE TORNILLERÍA Y FERRETERÍA AAA

AV. ALVARO OBREGÓN #524, COL. ESPERANZA
C.P. 24080 CAMPECHE, CAMP. TEL.: 981 815 2808

CHIAPAS FIX FERRETERÍAS

AV. CENTRAL SUR #27, COL. CENTRO, C.P. 30700,
TAPACHULA, CHIS. TEL.: 962 118 4083

CHIHUAHUA SUCURSAL CHIHUAHUA

AV. SILVESTRE TERRAZAS #128-11, PARQUE INDUSTRIAL
BAFAR, CARRETERA MÉXICO CUAUHTEMOC, C.P. 31415,
CHIHUAHUA, CHIH. TEL.: 614 434 0052

MEXICO CITY FIX FERRETERÍAS

EL MONSTRUO DE CORREGIDORA, CORREGIDORA # 35,
COL. CENTRO, C.P. 06060, CUAUHTEMOC, CDMX.
TEL.: 55 5522 5031 / 5522 4861

COAHUILA SUCURSAL TORREÓN

CALLE METAL MECÁNICA #280, PARQUE INDUSTRIAL
ORIENTE, C.P. 27278, TORREÓN, COAH.
TEL.: 871 209 68 23

COLIMA BOMBAS Y MOTORES BYMTESA DE MANZANILLO

BLVD. MIGUEL DE LA MADRID #190, COL. 16 DE
SEPTIEMBRE, C.P. 28239, MANZANILLO, COL.
TEL.: 314 332 1986 / 332 8013

DURANGO TORNILLOS ÁGUILA, S.A. DE C.V.

MAZURIÓ #200, COL. LUIS ECHEVERRÍA, DURANGO,
DGO. TEL.: 618 817 1946 / 618 818 2844

ESTADO DE MÉXICO SUCURSAL CENTRO JILOTEPEC

PARQUE INDUSTRIAL # 1, COL. PARQUE INDUSTRIAL
JILOTEPEC, JILOTEPEC, EDO. DE MÉX. C.P. 54257
TEL.: 761 782 910 EXT. 5728 Y 5102

GUANAJUATO C.I.A. FERRETERA NUEVO MUNDO S.A. DE C.V.

AV. MÉXICO - JAPÓN #225, CD. INDUSTRIAL, C.P. 38010,
CELAYA, GTO. TEL.: 461 617 7578 / 79 / 80 / 88

GUERRERO CENTRO DE SERVICIO ECLIPSE

CALLE PRINCIPAL MZ.1 LT. 1, COL. SANTA FE, C.P. 39010,
CHILPANCINGO, GRO. TEL.: 747 478 5793

HIDALGO FERREPRECIOS S.A. DE C.V.

LIBERTAD ORIENTE #304 LOCAL 30, INTERIOR DE PASAJE
ROBLEDO, COL. CENTRO, C.P. 43600, TULANCINGO,
HGO. TEL.: 775 753 6615 / 775 753 6616

JALISCO SUCURSAL GUADALAJARA

AV. ADOLFO B. HORN # 6800, COL. SANTA CRUZ DEL
VALLE, C.P.: 45655, TLALOMULCO DE ZUÑIGA, JAL.
TEL.: 33 3606 5285 AN 90

MICHOACÁN FIX FERRETERÍAS

AV. PASEO DE LA REPÚBLICA #3140-A, COL.
EX-HACIENDA DE LA HUERTA, C.P. 58050, MORELIA,
MICH. TEL.: 443 334 6858

MORELOS FIX FERRETERÍAS

CAPITÁN ANZURES #95, ESQ. JOSÉ PERDIZ, COL.
CENTRO, C.P. 62740, CUAUTLA, MOR.
TEL.: 735 352 8951

NAYARIT HERRAMIENTAS DE TEPIC

MAZATLÁN #117, COL. CENTRO, C.P. 63000, TEPIC, NAY.
TEL.: 311 258 040

NUEVO LEÓN SUCURSAL MONTERREY

CARRETERA LAREDO #300, 1B MONTERREY PARKS,
COLONIA PUERTA DE ANÁHUAC, C.P. 66052, ESCOBEDO,
NUEVO LEÓN, TEL.: 81 8352 8791 / 81 8352 8790

OAXACA FIX FERRETERÍAS

AV. 20 DE NOVIEMBRE #910, COL. CENTRO, C.P. 68300,
TUXTEPEC, OAX. TEL.: 287 106 3092

PUEBLA SUCURSAL PUEBLA

AV. PERIFERICO #2-A, SAN LORENZO ALMECATLA,
C.P. 72710, CUAUTLACINGO, PUE.
TEL.: 222 282 8282 / 84 / 85 / 86

QUERÉTARO ARU HERRAMIENTAS S.A. DE C.V.

AV. PUERTO DE VERACRUZ #110, COL. RANCHO DE
ENMEDIO, C.P. 76842, SAN JUAN DEL RÍO, QRO.
TEL.: 427 268 4544

QUINTANA ROO FIX FERRETERÍAS

CARRETERA FEDERAL MZ. 46 LT. 3 LOCAL 2, COL. EJIDAL,
C.P. 77710 PLAYA DEL CARMEN, Q.R.
TEL.: 984 267 3140

SAN LUIS POTOSÍ FIX FERRETERÍAS

AV. UNIVERSIDAD #1850, COL. EL PASEO, C.P. 78320,
SAN LUIS POTOSÍ, S.L.P. TEL.: 444 822 4341

SINALOA SUCURSAL CULIACÁN

AV. JESÚS KUMATE SUR #4301, COL. HACIENDA DE LA
MORA, C.P. 80143, CULIACÁN, SIN.
TEL.: 667 173 9139 / 173 8400

SONORA FIX FERRETERÍAS

CALLE 5 DE FEBRERO #517, SUR LT. 25 MZ. 10, COL.
CENTRO, C.P. 85000, CD. OBREGÓN, SON.
TEL.: 644 413 2392

TABASCO SUCURSAL VILLAHERMOSA

CALLE HELIO LOTES 1, 2 Y 3 MZ. #1, COL. INDUSTRIAL,
2A ETAPA, C.P. 86010, VILLAHERMOSA, TAB.
TEL.: 993 353 7244

TAMAULIPAS VM ORINGS Y REFACCIONES

CALLE ROSITA #527 ENTRE 20 DE NOVIEMBRE Y GRAL.
RODRIGUEZ, FRACC. REYNOSA, C.P. 88780, REYNOSA,
TAMS. TEL.: 899 926 7552

TLAXCALA SERVICIOS Y HERRAMIENTAS INDUSTRIALES

PABLO SIDAR #132, COL. BARRO DE SAN BARTOLOMÉ,
C.P. 90970, SAN PABLO DEL MONTE, TLAX.
TEL.: 222 271 7502

VERACRUZ LA CASA DISTRIBUIDORA TRUPER

BLVD. PRIMAVERA ESQ. HORTENSIA S/N, COL.
PRIMAVERA C.P. 93308, POZA RICA, VER.
TEL.: 782 823 8100 / 826 4848

YUCATÁN SUCURSAL MÉRIDA

CALLE 33 #600 Y 602, LOCALIDAD ITZINCAB Y MULSAY,
MPIO. UMÁN, C.P. 97390, MÉRIDA, YUC.
TEL.: 999 912 2451

Code

29017

Model

SOIN-310MP

Brand**PRETUL®**

Warranty. Duration: 1 year. Coverage: parts, components, and labor against manufacturing or operational defects, except when used under conditions other than normal, not operated according to the instructions, altered, or repaired by unauthorized personnel not authorized by TRUPER®. To enforce the warranty, present the product, sealed policy, invoice, or receipt, at the establishment where you purchased it or at Corregidora 35, Centro, Cuauhtémoc, CDMX, 06060, where you can also purchase parts, components, consumables, and accessories. It includes transportation expenses for the product resulting from its service network compliance. Tel. **800-018-7873**. Made in/Hecho en China. Importer **TRUPER, S.A. de C.V.** Parque Industrial 1, Parque Industrial Jilotepec, Jilotepec, Edo. de Méx. C.P. 54257, Tel. 761 782 9100.



Stamp of the business. Delivery date:

WWW.TRUPER.COM

Sello del establecimiento comercial. Fecho de entrega:



Garantía. Duración: 1 año. Cobertura: Piezas, componentes y mano de obra contra defectos de fabricación ofuncionamiento, excepto si se uso en condiciones distintas a las normales; cuando no fue operado conforme instrucciones; fue alterado o preparado por personal no autorizado por TRUPER®. Para hacer efectiva la garantía, presentar el producto, poliza sellada o recibo o comprobante, así como el establecimiento donde lo compró o en Corregidora 35, Centro, Cuautitlán, CDMX, 06060, donde también podrá adquirir partes, componentes, consumibles y accesorios, incluye los gastos de transportación del producto que deviven de su cumplimiento de acuerdo de servicio. Tel. 800-018-7873. Made in/Hetido en China. Importador TRUPER, S.A. de C.V. Padrone su red de servicios.

Código	Modelo	Marcas	PRTUL	SOM-310MP	29017
--------	--------	--------	-------	-----------	-------

**Póliza de
garantía**

PRTUL

<p>MORELOS</p> <p>FIX FERRERIALES</p> <p>CAPITAN AÑUELAS #45, ESO, JOSE PEREZ, COL. MEXICALI</p> <p>TEL.: 755 352 8931</p> <p>NAVARRA</p> <p>HERMILINERAS DE TEPIC</p> <p>MZ211 #100, COL. CENTRO, C.P. 63000, TEPIC, NAY.</p> <p>TEL.: 311 258 0540</p> <p>NUEVO LEÓN</p> <p>SCGRSLA MONTERRÍEY</p> <p>CARREFA LA RIBERA #500, 1B MONTERREY PARKS, MEXICO 25200, TEL.: 81 352 8791 / 81 352 8790</p> <p>QUERÉTARO</p> <p>AUH HERMILINERAS S.A DE C.V.</p> <p>EMBALIO, C.P. 76001, C.P. 76001, SAN JUAN DEL RIO, QRO.</p> <p>TEL.: 427 268 2828 / 84 / 85 / 86</p> <p>QUINTANA ROO</p> <p>FIX FERRERIALES</p> <p>CP 77701 PLAZA DEL CARMEN, Q.R.</p> <p>CP 77701 PLAZA DEL CARMEN, Q.R.</p> <p>TEL.: 984 726 1310</p> <p>SAN LUIS POTOSÍ</p> <p>SCGRSLA CLAUDIO</p> <p>AV. JESÚS KUMAIE SUR #430, COL. HACIENDA DE LA</p> <p>UNIVERSIDAD, C.P. 80000, CD. OBREGÓN, SON.</p> <p>TEL.: 667 753 1938 / 173 8400</p> <p>SINALOA</p> <p>SCGRSLA CLAUDIO</p> <p>AV. JESÚS KUMAIE SUR #430, COL. HACIENDA DE LA</p> <p>UNIVERSIDAD, C.P. 80000, CD. OBREGÓN, SON.</p> <p>TEL.: 667 753 1938 / 173 8400</p> <p>SONORA</p> <p>FIX FERRERIALES</p> <p>CD. OBREGÓN, C.P. 85000, CD. OBREGÓN, SON.</p> <p>TEL.: 664 413 3292</p> <p>TABASCO</p> <p>SCGRSLA HERMOSA</p> <p>CALLE 100 LOTES 1, 2 Y 3 KM #1, COL. INDUSTRIAL,</p> <p>DE LA PLATA, C.P. 86100, VILLAHOMOSA, TAB.</p> <p>TEL.: 993 353 7244</p> <p>TAJAMULCAS</p> <p>VM ORINGS Y REFRIGORINES</p> <p>CALLE 100 LOTES 1, 2 Y 3 KM #1, COL. INDUSTRIAL,</p> <p>DE LA PLATA, C.P. 86100, VILLAHOMOSA, TAB.</p> <p>TEL.: 993 353 7244</p> <p>TOLUCA</p> <p>ERHICOS DISTRIBUIDORA TRUPER</p> <p>PABLO SIARIO #125 COL. APARDO DE SAN ARISTOTELES,</p> <p>C.P. 42000, TEL.: 222 271 7520</p> <p>TRENCALÁ</p> <p>ERHICOS DISTRIBUIDORA TRUPER</p> <p>PABLO SIARIO #125 COL. APARDO DE SAN ARISTOTELES,</p> <p>C.P. 42000, TEL.: 222 271 7520</p> <p>VERACRUZ</p> <p>LA CASA DISTRIBUIDORA TRUPER</p> <p>BUDI PRIMERIA L3-Q, HORTESSA S/N, COL.</p> <p>TEL.: 782 823 8100 / 826 8484</p> <p>YUCATÁN</p> <p>SCGRSLA MERIDA</p> <p>MPILO, MNA., C.P. 79390, MERIDA, YUC.</p> <p>TEL.: 999 912 451</p>	<p>ACUSCALIENTES</p> <p>DE TODO PARA LA CONSTRUCCIÓN</p> <p>GRAL. BARRAGÁN #121, COL. GERMÁN, C.P. 20030.</p> <p>ACUACALIENTES, C.G.S, TEL.: 499 994 0537</p> <p>BAJA CALIFORNIA</p> <p>FE FIX FERRERIAS</p> <p>FELEP ANUELES ESQ., BLVZ CORTINAS S/N, COL. PUEBLO NUEVO, C.P. 23620, C.D. CONSULTORIO, B.C.S.</p> <p>TEL.: 693 152 1115</p> <p>BAJA CALIFORNIA SUR</p> <p>FE FIX FERRERIAS</p> <p>FELEP ANUELES ESQ., BLVZ CORTINAS S/N, COL. PUEBLO NUEVO, C.P. 23620, C.D. CONSULTORIO, B.C.S.</p> <p>TEL.: 694 995 5100</p> <p>CHIAPAS</p> <p>FE FIX FERRERIAS</p> <p>AV. ALVARO OBREGÓN #24, COL. SEFARNZA</p> <p>C.P. 24080 CAMPECHE, CAMP. TEL.: 981 815 2808</p> <p>CHIHUAHUA</p> <p>SCGRSLA CHIHUAHUA</p> <p>AV. CENTRAL #27, COL. CENTRO, C.P. 30700.</p> <p>TAPACHULA, CHIH. TEL.: 614 434 0052</p> <p>COAHUILA</p> <p>SCGRSLA TORREN</p> <p>COL. MONTURAS DE CORREDORIA CORREDORA #35,</p> <p>CALLE MELA MELA MEXICALI #280, PARGUE INDUSTRIAL</p> <p>TEL.: 55 5522 5031 / 5522 8013</p> <p>COLIMA</p> <p>BOMBS Y MOTORES BRYMESA DE MANZANILLO</p> <p>SEPTIMERO, C.P. 28239, MANGANILLO, COL. 16 DE MARZO, TEL.: 81 871 946 / 818 2044</p> <p>COQUILLO TUYUCA</p> <p>FE FIX FERRERIAS</p> <p>PROYECTO INDUSTRIAL #1, COL. PARGUE INDUSTRIAL</p> <p>TEL.: 761 782 010 EXT. 5728 0102</p> <p>GUANAJAUTA</p> <p>CAJA DE SERVICIOS MUNICIPAL S.A. DE C.V.</p> <p>AV. MEXICO - APUN #220, CD. INDUSTRIAL, C.P. 38010.</p> <p>CHIAPAS, TEL.: 461 617 7528 / 79 / 88</p> <p>HIDALGO</p> <p>CAJA DE SERVICIOS MUNICIPAL S.A. DE C.V.</p> <p>CLAVE PRINCIPAL MZ. 1, COL. SANTA FE, C.P. 393010.</p> <p>CHIAPAS, TEL.: 471 478 5793</p> <p>JALISCO</p> <p>SUGRSLA GUADALAJARA</p> <p>VALLE C.P. 44655, TIAJOMULCO DE ZUMAÑA, JAL.</p> <p>TEL.: 33 966 2525 AL 90</p> <p>MICHOACÁN</p> <p>FE FIX FERRERIAS</p> <p>AV. PASEO DE LA REPUBLICA #310-A, COL. SANTO CRISTO DEL ESTEBAN COATZACOALCO, C.P. 58050, MORELIA.</p> <p>MICH., TEL.: 443 344 8858</p>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

En caso de tener algún problema para contratar un Centro de Servicio Autorizado TRUPER, consulte nuestra página web WWW.TRUPER.COM donde obtendrá un listado actualizado, o llame al 800 690-6990 u 800 018-7873 donde le informarán cuál es el centro de servicio más cercano.



PRETUL

Solución de problemas

Solución

La luz de protección • La soldadora no enciende con ventilación adecuada. • Mantenga la soldadora separada de cualquier pared al menos 30 cm para permitir que el aire circule.

El control de ajuste de • El potenciómetro está roto. • Aclara un Centro de Servicio Autorizado TRUPER para reemplazar el potenciómetro.

El ventilador no funciona o gira muy lentamente. • Ventilador descompuerto. • Aclara un Centro de Servicio Autorizado TRUPER para reemplazar el ventilador.

No hay tensión de • Tensión alta, tensión baja o falta una fase. • La soldadora se recuperará una vez que la temperatura remplace el interruptor.

El circuito abierto. • La soldadora se está sobrecalentando. • Aclara un Centro de Servicio Autorizado TRUPER para reparar el interruptor.

Las conexiones + y - se calientan. • La medida del cable es muy pequeña. • Reemplace el cable por otro dentro de las conexiones. • Cambios de temperatura. • La medida del cable es muy pequeña. • Reemplace el cable por otro dentro de las conexiones.

La fuente de energía • La soldadora se ha sobrecalentado. • No hay flama. Es normal que el suministro de energía sea constante. • La conexión de polaridad de salida no es correcta.

Si los problemas persisten a pesar de realizar las acciones correctivas recomendadas, contacte a un Centro de Servicio Autorizado TRUPER.

Problema	Causa	Solución
La soldadora no enciende con ventilación adecuada.	Mantenga la soldadora separada de cualquier pared al menos 30 cm para permitir que el aire circule.	La luz de protección

Problema	Causa	Solución
El control de ajuste de	El potenciómetro está roto.	Aclara un Centro de Servicio Autorizado TRUPER para reemplazar el potenciómetro.
El ventilador no funciona o gira muy lentamente.	Ventilador descompuerto.	Aclara un Centro de Servicio Autorizado TRUPER para reemplazar el ventilador.
No hay tensión de	Tensión alta, tensión baja o falta una fase.	La soldadora se recuperará una vez que la temperatura remplace el interruptor.
El circuito abierto.	La soldadora se está sobrecalentando.	Aclara un Centro de Servicio Autorizado TRUPER para reparar el interruptor.

Problema	Causa	Solución
El control de ajuste de	El potenciómetro está roto.	Aclara un Centro de Servicio Autorizado TRUPER para reemplazar el potenciómetro.
El ventilador no funciona o gira muy lentamente.	Ventilador descompuerto.	Aclara un Centro de Servicio Autorizado TRUPER para reemplazar el ventilador.
No hay tensión de	Tensión alta, tensión baja o falta una fase.	La soldadora se recuperará una vez que la temperatura remplace el interruptor.
El circuito abierto.	La soldadora se está sobrecalentando.	Aclara un Centro de Servicio Autorizado TRUPER para reparar el interruptor.

Problema	Causa	Solución
El control de ajuste de	El potenciómetro está roto.	Aclara un Centro de Servicio Autorizado TRUPER para reemplazar el potenciómetro.
El ventilador no funciona o gira muy lentamente.	Ventilador descompuerto.	Aclara un Centro de Servicio Autorizado TRUPER para reemplazar el ventilador.
No hay tensión de	Tensión alta, tensión baja o falta una fase.	La soldadora se recuperará una vez que la temperatura remplace el interruptor.
El circuito abierto.	La soldadora se está sobrecalentando.	Aclara un Centro de Servicio Autorizado TRUPER para reparar el interruptor.

Símbolos

- Si el técnico de servicios debe limpiar el polvo de la soldadora con aire comprimido. En caso haber mucho polvo, se debe limpiar de inmediato. Bajo condiciones normales, se requiere limpiar una vez al año. En caso de que la soldadora sea expuesta a mucha polvo, la limpieza debe realizarla cada tres meses.
 - Durante la limpieza debe revisar que no haya partes o componentes sueltos en la soldadora.
 - Mantenga la clavija del cable de la soldadora en buen estado.
 - La clavija debe revisarse antes de cada uso.

Almacenamiento


Mantenimiento regular

A) ATENCIÓN • Solo personal calificado debe hacer las preparaciones. Se recomienda visitar un Centro de Servicio Autorizado TRUPER para la soldadura y adquirir suministros de accesorios.

- El uso incorrecto y una limpieza regular de la herramienta es vital de la soldadura.

Mantenimiento

PRETUL





sostenga el electrodo por la parte recubierta.

- ATENCIÓN** • El electrodo se quema a alta temperatura. No intente manipular los restos del electrodo con la mano. Ponga los restos en un contenedor de metal. • Abra la tapa del porta electrodo para sostener el electrodo nuevo por el extremo sin quemárselo. No

Reemplazo de electrodo

Las soluciones que ofrecen los proveedores de servicios de telecomunicaciones en el sector público se basan en la utilización de sistemas de eliminación de ruido en las señales de televisión. Estos sistemas consisten en una combinación de amplificadores y filtros que reducen el ruido y mejoran la calidad de la señal. Los proveedores de servicios de telecomunicaciones ofrecen estos sistemas a precios competitivos y con instalaciones y mantenimiento incluidos.

Sobre cargo



- Pueden sentir partículas despedidas al golpear o cepillar la escoria. Utilice protección para los ojos y mantenga a las personas alejadas.

- Al terminar el trabajo de soldado, utilice el cepillo de alambre incluido para retirar la escoria de la superficie del

Retiro de escoria

- Qumienche a soldar una vez que e mantinenido siempre la punta del apoyado en la pieza de trabajo, podria de trabajos. Si realiza la soldadura de la otra pieza de la misma forma se obtendria una soldadura seria de mala calidad.

- Coloque el interruptor (**B**) en posición de encendido (I).
- Ajuste la potencia de control del comineco (**C**) hasta alcanzar la corriente deseada para el tubo.
- Sostenga el porta electrodos de la manera más cómoda.
- Posicione el tubo en la parte inferior del electrodo.
- Deline la pista de trabajo en el suelo y distancie con respecto a los bordes.
- La pieza de trabajo debe ser constante y uniforme.
- Deline la punta del electrodo hacia la unión a trabajar para generar el arco eléctrico y comience a soldar.

Soldadura

- Esiéate de las piezas de metal que se aplican a la soldadura.
- Las uniones entre laminas con calorres mayores de 1/8" (3 mm) deben ser biseladas para que la soldadura sea adecuada (A).


- Los factores que intervienen en el proceso de soldadura son muchos: corriente requerida, distancia entre el electrodo y la pieza de trabajo, velocidad y dirección de tracción, grosor y tipo del material, posición de la pieza de trabajo, ancho de electrodo, además de calidad, medida y regulamiento del electrodo.
- Garantizar un buen resultado de soldadura.

- Solo con experiencia, práctica y cuidado se puede

Preparativos

Puesta en marcha

PRETUL



PRETUL

Instalación (SMAW)

Conexiones

- Necesario consultar la información de la sección “Requerimientos eléctricos”, en la página 3.
- Las conexiones rápidas del porta electrodos y la placa para alternarán rápidamente en las salidas del panel frontal para que el usuario no tenga que insertar y girar un cuadro de vuela en cada conexión.
- Conecte la placa para alternar (C) a la placa de trabajo.
- Conecte el cable de la placa para alternar a la salida (+).
- Conecte la placa para alternar a la salida (-).

Polaridad inversa

- Conecte la placa para alternar (C) a la placa de trabajo.
- Conecte el cable de la placa para alternar al borne de positiva (+) de la soldadora.
- Conecte la configuración gruesa con electrodos básicos, que reduce mayor penetración con electrodos básicos, lo que hace ideal para soldar piezas gruesas.
- Esta configuración genera más calor en la pieza de trabajo, lo que reduce el consumo de energía.
- Conecte el cable de la placa para alternar a la salida (-).


Polaridad directa (B)

- Conecte el cable de la amperímetro (D) a la red de alumbrado en la salida (+).
- Antes de usar la soldadora, debe conectar el cable de la amperímetro a la tierra ya que hace que el diseño esté correctamente puesta a tierra. No debe desinstalar el cable de la amperímetro para soldar piezas gruesas.

ADVERTENCIA


• Algunas aplicaciones requieren una tensión de corriente constante (127 V).

Coloque un electrodo
adelante para el trabajo
en el porta electrodo.



Mesa de
trabajo
de metal

Mesa de
trabajo
de metal



- Antes de usar la soldadora, debe conectar el cable de la amperímetro (D) a la red de alumbrado en la salida (+).
- Algunas aplicaciones requieren una tensión de corriente constante (127 V).

• Antes de usar la soldadora, debe conectar el cable de la amperímetro (D) a la red de alumbrado en la salida (+).

- Conecte el cable de la amperímetro (D) a la red de alumbrado en la salida (+).
- Conecte la placa para alternar (C) a la placa de trabajo.
- Conecte el cable de la placa para alternar a la salida (+).
- Conecte el cable de la placa para alternar a la salida (-).

• Conecte la placa para alternar (C) a la placa de trabajo.


- Conecte la placa para alternar (C) a la placa de trabajo.
- Conecte la configuración gruesa con electrodos básicos, que reduce mayor penetración con electrodos básicos, lo que hace ideal para soldar piezas gruesas.
- Esta configuración genera más calor en la pieza de trabajo, lo que reduce el consumo de energía.

Polaridad directa (A)

- Conecte la placa para alternar (C) a la placa de trabajo.
- Conecte el cable de la placa para alternar a la salida (-).
- Conecte el cable de la placa para alternar a la salida (+).

Polaridad inversa

Para soldar compatible, tal como el CAB-200 marca TRUPER.
Para mejores resultados, utilice un juego de cables con pinza.



- En el caso de requerir extensiones entre la soldadora y la pieza de trabajo, se debe aumentar el cable de soldadura para mantener la salida de energía del cable de soldadura a una medida que no sea menor a 4 V.
- En el caso de requerir extensiones entre la soldadora y la pieza de trabajo, se debe aumentar el cable de soldadura para mantener la salida de energía del cable de soldadura a una medida que no sea menor a 4 V.

- * La corriente de fusible del fusible es el doble de su corriente nominal.
- Fusible (corriente nominal de trabajo) = 30 A (*)
- Alambre eléctrico = 2.5 mm²
- Interruptor = 30 A





A ATENCIÓN • Es calibre del cable del suministro eléctrico debe cumplir con los siguientes requisitos:

la soldadora, condensada con el voltaje del suministro eléctrico.

A ATENCIÓN • Confirmé siempre que el voltaje de la conexión de entrada, estipulado en la placa de información eléctrica.

A ATENCIÓN • La conexión a tierra debe realizarse por un profesional en electricidad.

A ATENCIÓN • Es calibre del cable condensado en paralelo, conectados en serie.



la soldadora adquirira la silla apropiada instalada por un electricista calificado.

A ADVERTENCIA • No modifique la clavija provista. Si la clavija no ajusta a

el cable, adquiera la silla apropiada para su instalación por un electricista calificado.

acuerdo con todos los códigos locales.

debe estar conectada a una entrada que es adecuada y autorizada para la clavija.

eléctrico que tiene un conductor a tierra y otro con conexión a tierra. La clavija

debe sufrir una descarga eléctrica. Esta herramienta está equipada con un cable

de seguridad con resistencia mínima para la conexión eléctrica, lo que reduce el riesgo

de descargas eléctricas. La conexión a tierra prueba una

A ADVERTENCIA • En el caso de fallas o averías, la conexión a tierra provee una

seguridad adicional en caso de averías o averías.



A ADVERTENCIA • Antes de obtener acceso a las terminales, todos los circuitos de alimentación deben ser



de liquidos durante su operación. No la exponga a la lluvia, líquidos y/o humedad.

La construcción del sistema eléctrico de esta herramienta es adecuada para satisfacer los criterios de seguridad establecidos.

Centro de Servicio Autorizado TRUPER, con el fin de evitar algún riesgo de descripción o accidente considerable.

El cable de alimentación se daña, este debe ser reemplazado por el fabricante o un

A ADVERTENCIA • Si el cable de alimentación se rompe o se rompe, la clase de aislamiento térmico de los devanados: Clase H

El cable de alimentación tiene sujetacables tipo Y. La clase de construcción de la herramienta es: Aislamiento básico

La clase de aislamiento térmico de los devanados: Clase H

Los valores de tensión de la herramienta están dados a una temperatura de 20 °C. A temperaturas mayores, el uso de trabajo puede reducirse.

6 min de trabajo por 4 min de descanso.

90%

Círculo de trabajo nominal • 2.5 mm [3/32"] - 3 mm [1/8"]

Diametro de electrode (SMAW) •

14 AWG x 3C con temperatura de aislamiento de 105 °C

Condutores •

Aislamiento • Clase I Grado IP • IP21S

Medidas • 10 cm x 24 cm x 15 cm Peso • 2.4 kg

Tensión de entrada • 20 A - 100 A

Factor de potencia • 0.82

Tensión de circuito abierto • 82 V.C.

Capacidad de entrada nominal • 3.5 kVA

Frecuencia • 50 Hz / 60 Hz

Tensión de entrada • 127 V ~

Soldadora inversora •

Descripción •

Código • 29017

SON-310MP

- 4** Realice **MANTENIMIENTO** periódico a su máquina (página 10).
- 4** Se recomienda utilizar una extensión calibre **14 AWG** (2.08 mm^2) y conectar en un **CENTRO DE CARGA INDIPENDIENTE**.

- THERMAL** La máquina cuenta con un **PROTECTOR TÉRMICO** que en caso de sobrecalefacción se activa la soldadora por 15 minutos y vuelve a encenderla.
- PROTECT** apaga la soldadora y enciende la luz LED de protección térmica. Si esto sucede, deje

- DÍAMETROS DE ELECTRODO REVESTIDO:** Proceso SMAW 6013-001 2.5 mm ($3/32''$), 3 mm ($1/8''$) | 7018 2.5 mm ($3/32''$)
- RANGO DE CORRIENTE DE SALIDA:** Conectada a $127 \text{ V} \sim$ 20 A - 100 A
- RESPECTO AL CICLO DE TRABAJO:** 6 minutos de trabajo por 4 minutos de descanso

RECOMENDACIONES DE USO Y CUIDADOS

- 14** Poliza de garantía.
- 13** Centros de servicio autorizados.
- 12** Notas.
- 11** Solución de problemas.
- 10** Simbología.
- 10** Mantenimiento.
- 8** Puesta en marcha.
- 7** Instalación (SMAW).
- 6** Partes.
- 5** Soldadores inversores.
- 4** Advertencias de seguridad para uso de herramientas eléctricas.
- 3** Requerimientos técnicos.
- 3** Especificaciones técnicas.
- Para poder sacar el máximo provecho de la herramienta, alargar su vida útil, hacer válida la garantía en caso de ser necesario y evitar riesgos o lesiones graves, es fundamental leer este instructivo por completo antes de usar la herramienta.
- Guarde este instructivo para futuras referencias.
- Los gráficos de este instructivo para futuras referencias, pueden variar del aspecto real de la referencia, pero no tienen validez.
- Nota:
- Solución de problemas
- Puesta en marcha
- Instalación (SMAW)
- Partes
- Soldadores inversores
- Advertencias de seguridad para uso de herramientas eléctricas
- Para herramientas generales de seguidad
- Requerimientos técnicos
- Especificaciones técnicas

A) ATENCIÓN


Indice

PRETUL



Lea este instructivo por completo
antes de usar la herramienta.

ATENCIÓN



Código: 29017
Modelo: S01N-
310MP
Este instructivo es para:

60%
Círculo de trabajo

Soldadora inversora

Instructivo de

PRETUL

ESPAÑOL
ENGLISH