

INSTRUCCIONES

La superficie a pintar debe estar limpia, seca, libre de polvo, grasa, óxido y restos de pintura. Utilice papel periódico para proteger el área alrededor de la superficie a pintar. Agite dos minutos antes de aplicar y periódicamente durante la aplicación para lograr un acabado uniforme. Rocíe a una distancia de 20 cm a 25 cm de la superficie con el envase en posición vertical. Aplique capas ligeras y deje secar antes de aplicar una segunda mano. Al terminar el trabajo, para limpiar la válvula, coloque el envase boca abajo y presione la válvula hasta que deje de salir el esmalte. **NOTA:** En caso de que la válvula se tape, utilice una aguja o alambre delgado y tñer para destaparla. **Para obtener colores brillantes aplique primero una capa de esmalte PRETUL® color blanco. Para aplicaciones en superficies de madera, metal, yeso, plástico rígido, porcelana, etc.**

INSTRUCTIONS

The surface to be painted must be clean, dry, free of dust, grease, oxides and paint residues. Use newspaper to protect the area around the surface to be painted. Shake for two minutes before applying and periodically during application to achieve a uniform finish. Spray at a distance of 20 cm a 25 cm (8 inches - 10 inches) from the surface with the container in vertical position. Apply light coats and let dry before applying a second coat. When finished, clean the valve, turn the container upside down and press the valve until the enamel stops coming out. **NOTE:** In case the valve is clogged, use a thin needle or wire and thinner to unclog it.

For bright colors, first apply a layer of PRETUL white paint. For applications on wood, metal, plaster, rigid plastic, porcelain, etc.