

ENGLISH  
ESPAÑOL

TRUPER®  
ERGO-PRO

Manual


# Angle grinder

1.1 Hp

Power

4½"

Disc



Applies for:

Code

Model

100735

ERGO-4580-2

# ERGO-4580-2

 CAUTION



Read this manual thoroughly  
before using the tool.



Technical Data .....	3
Power Requirements .....	3
 General power tool safety warnings .....	4
 Safety warnings for angle grinders .....	5
Parts .....	7
Assembly .....	7
Start Up .....	8
Maintenance .....	9
Notes .....	10
Authorized Service Centers .....	11
Warranty Policy .....	12

**CAUTION**

To gain the best performance of the tool, prolong the duty life, make the Warranty valid if necessary, and to avoid hazards of fatal injuries please read and understand this Manual before using the tool.

Keep this manual for future references.

The illustrations in this manual are for reference only. They might be different from the real tool.



# Technical Data

ERGO-4580-2

**TRUPER®  
ERGO-PRO**

Code	•	100735
Description	•	Angle grinder
Discs	•	4 1/2"
Voltage	•	220 V~
Frequency	•	50 Hz / 60 Hz
Current	•	3.6 A
Power	•	1.1 Hp
Speed	•	12 000 RPM
Duty cycle	•	30 minutes work per 15 minutes idle. Maximum 3 hours per day.
Conductors	•	H05VV-F 2 x 0.75 mm <sup>2</sup>
Insulating	•	Class II IP Grade • IP20

Power Cord Grips used in this product: Type Y

Tool Build Quality: Reinforced insulation.

Thermal insulation on motor winding: Class H


**⚠ WARNING** Avoid the risk of electric shock or severe injury. When the power cable gets damaged it should only be replaced by the manufacturer or at a **TRUPER®** Authorized Service Center. The build quality of the electric insulation is altered if spills or liquid gets into the tool while in use. Do not expose to rain, liquids and/or dampness.

**⚠ WARNING** Before gaining access to the terminals all power sources should be disconnected.



## Power requirements

**⚠ WARNING** Tools with double insulation are equipped with a 220 V~ plug. Do not alter the plug in any way. Double insulation eliminates the need of a grounded third power cord with three prongs or a grounded power connection.



**⚠ WARNING** When using an extension cable, verify the gauge is enough for the power that your product needs. A lower gauge cable will cause voltage drop in the line, resulting in power loss and overheating. The following table shows the right size to use depending on cable's length and the ampere capability shown in the tool's nameplate. When in doubt use the next higher gauge.

Ampere Capacity	Number of Conductors	Extension gauge from 5.9' to 49.2'   higher than 49.2'
from 0 A and up to 11 A		18 AWG(*)
from 11 A and up to 15 A		16 AWG
from 15 A and up to 17 A		14 AWG
from 17 A and up to 23 A	3	12 AWG
		10 AWG
		8 AWG

\* It is safe to use only if the extensions have a built-in artifact for over current protection.

AWG = American Wire Gauge. Reference: NMX-J-195-ANCE

ENGLISH

**⚠ WARNING! Read carefully all safety warnings and instructions listed below.** Failure to comply with any of these warnings may result in electric shock, fire and / or severe damage. **Save all warnings and instructions for future references.**

**Work area****Keep your work area clean, and well lit.**

Cluttered and dark areas may cause accidents.

**Never use the tool in explosive atmospheres, such as in the presence of flammable liquids, gases or dust.**

Sparks generated by power tools may ignite the flammable material.

**Keep children and bystanders at a safe distance while operating the tool.**

Distractions may cause loss of control.

**Electrical Safety****The tool plug must match the power outlet. Never modify the plug in any way. Do not use any adapter plugs with grounded power tools.**

Modified plugs and different power outlets increase the risk of electric shock.

**Avoid body contact with grounded surfaces, such as pipes, radiators, electric ranges and refrigerators.**

The risk of electric shock increases if your body is grounded.

**Do not expose the tool to rain or wet conditions.**

Water entering into the tool increases the risk of electric shock.

**Do not force the cord. Never use the cord to carry, lift or unplug the tool. Keep the cord away from heat, oil, sharp edges or moving parts.**

Damaged or entangled cords increase the risk of electric shock.

**When operating a tool outdoors, use an extension cord suitable for outdoor use.**

Using an adequate outdoor extension cord reduces the risk of electric shock.

**If operating the tool in a damp location cannot be avoided, use a ground fault circuit interrupter (GFCI) protected supply.**

Using a GFCI reduces the risk of electric shock.

**Personal safety****Stay alert, watch what you are doing and use common sense when operating a tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication.**

A moment of distraction while operating the tool may result in personal injury.

**Use personal protective equipment. Always wear eye protection.**

Protective equipment such as safety glasses, anti-dust mask, non-skid shoes, hard hats and hearing protection used in the right conditions significantly reduce personal injury.

**Prevent unintentional starting up. Ensure the switch is in the "OFF" position before connecting into the power source and / or battery as well as when carrying the tool.**

Transporting power tools with the finger on the switch or connecting power tools with the switch in the "ON" position may cause accidents.

**General power tool safety warnings****General power tool safety warnings****Remove any wrench or vice before turning the power tool on.**

Wrenches or vices left attached to rotating parts of the tool may result in personal injury.

**Do not overreach. Keep proper footing and balance at all times.**

This enables a better control on the tool during unexpected situations.

**Dress properly. Do not wear loose clothing or jewelry. Keep hair, clothes and gloves away from the moving parts.**

Loose clothes or long hair may get caught in moving parts.

**If you have dust extraction and recollection devices connected onto the tool, inspect their connections and use them correctly.**

Using these devices reduce dust-related risks.

**Power Tools Use and Care****Do not force the tool. Use the adequate tool for your application.**

The correct tool delivers a better and safer job at the rate for which it was designed.

**Do not use the tool if the switch is not working properly.**

Any power tool that cannot be turned ON or OFF is dangerous and should be repaired before operating.

**Disconnect the tool from the power source and / or battery before making any adjustments, changing accessories or storing.**

These measures reduce the risk of accidentally starting the tool.

**Store tools out of the reach of children. Do not allow persons that are not familiar with the tool or its instructions to operate the tool.**

Power tools are dangerous in the hands of untrained users.

**Service the tool. Check the mobile parts are not misaligned or stuck. There should not be broken parts or other conditions that may affect its operation. Repair any damage before using the tool.**

Most accidents are caused due to poor maintenance to the tools.

**Keep the cutting accessories sharp and clean.**

Cutting accessories in good working conditions are less likely to bind and are easier to control.

**Use the tool, components and accessories in accordance with these instructions and the projected way to use it for the type of tool when in adequate working conditions.**

Using the tool for applications different from those it was designed for, could result in a hazardous situation.

**Service****Repair the tool in a TRUPER® Authorized Service Center using only identical spare parts.**

This will ensure that the safety of the power tool is maintained.

# Safety warnings for angle grinders

This power tool is intended to function as a cutting tool. Read all safety warnings, instructions and specifications provided. Failure to follow the instructions outlined below may result in electric shock, fire and/or serious injury.

**TRUPER**  
**ERGO-PRO**

## Select the right disc

**CAUTION** • Never use discs with bigger diameter than the size required in the tool.

**WARNING** • Use only discs or accessories than 12 000 RPM speeds.

The rated speed of the accessory must be at least equal to the maximum speed marked on the tool. Accessories running faster than their rated speed may break and become detached.

**CAUTION** • Use only discs or accessories with an orifice that fits perfectly in the tool spindle.

**CAUTION** • Use only discs or accessories specifically designed for the chosen material.

Keep present people at a safe distance from the work area. Anyone entering the work area should wear personal protective equipment.

## Before operating the grinder

• Set apart some time and assess the job you are about to do. Pay attention to all the necessary cautions before starting to grind.

**DANGER** • Remove all the fastening wrenches from the tool. Otherwise they can shoot away causing severe injuries to the user.

**WARNING** • Double-check the guard. It should be perfectly fastened and in good working condition. Do not use the tool without a guard. Fragments of workpieces or a broken accessory can break off and cause damage beyond the immediate area of operation.

**CAUTION** • Double-check the disc. It should not be broken or cracked. Tap the disc gently with a wooden hammer and listen for a strange sound to learn if is cracked.

**DANGER** • Before plugging the tool, see if is in the OFF position. Otherwise the tool could start unexpectedly causing severe injuries.

**CAUTION** • Run the tool 30 seconds before using, to detect important vibration or any type of unusual movement. If detected, unplug the tool and take it to a **TRUPER**® Authorized Service Center.


**CAUTION** • See if the disc rotates freely.  
• Do not tighten the disc. It could brake.

**WARNING** • To work with small work pieces fasten with wrenches. Never use your hands to hold the piece.

**DANGER** Do not place saw discs for wood or a serrated blade. Such blades create frequent kickbacks and loss of control.

Operations for which this power tool is not designed may result in an accident and cause personal injury. It is not recommended to use this power tool in operations such as sanding, brushing or polishing.

Do not use accessories that are not specifically designed and recommended by the manufacturer.



Wrong way to operate the grinder

## While operating the grinder

**CAUTION** • Do not start the tool when the disc is touching the work piece.

**WARNING** • Wear safety glasses, gloves and an apron when using the tool.

**WARNING** • Keep the power cable or extension in the back of the tool. Avoid accidentally damaging the cables with the disc.

• If control of the power tool is lost, the cable may be cut or tangled and the operator's arm or hand may be pulled toward the rotary attachment.

**WARNING** • Never hold the tool by the power cable. Hold by the housing or auxiliary handle.

**CAUTION** • Hold the tool by the isolated parts. The cutting tool could come into contact with hidden wiring or its own cable. Making contact with a "live" wire causes the metal parts to electrify and give an electric shock to the user.

• Never let go of the power tool until the attachment comes to a complete stop.

• Never hit the work surface with the disc.

**CAUTION** • To get the best result with the grinding process, the inclination of the disc and the working surface should have an angle measuring 15° to 30°.

**DANGER** • When the disc is rotating never use the spindle lock to stop it. It is very dangerous and may cause injuries to the user.

**CAUTION** • Do not touch the disc or the working piece after grinding. Wait for them to cool down. Never try to cool them down using water or oil.


**WARNING** • Before checking, adjusting or changing discs, double-check the tool is not plugged in.

• Do not use the power tool near flammable materials.  
• Do not operate the tool while it is being transported to your side.

**DANGER** • Sparks caused when grinding may be dangerous. Use caution. Make sure sparks do not get into contact with skin or flammable substances.

• Gradually clean the tool's vents. The motor fan directs dust into the housing and excessive accumulation of metal dust can cause an electrical hazard.

• Do not use accessories that require liquid refrigerants. The use of water or other liquid refrigerants can result in an electric shock.



Right way to operate the grinder

**⚠ DANGER** **KICKBACK (Sharp Recoil)**

Kickback (sharp recoil) is a sudden reaction when a rotating wheel, backrest, brush, or other accessory gets stuck or snagged. Stalling or snagging causes rapid stalling of the rotary attachment which in turn causes the power tool to be forced uncontrollably in the direction opposite to the rotation of the attachment at the working point. An abrasive disc jams into the workpiece, the edge of the contacting disc can be pinched into the surface of the material causing the disc to stop, creating a kickback (sudden recoil). The disc may break and the fragments may jump in the direction of or away from the operator, depending on the direction of disc movement at the point of jamming.

Kickback can occur as a result of misuse of power tools and/or improper operating procedures or conditions and can be avoided by taking the precautions listed below:

- a) **Keep a firm grip on the power tool. Maintain your body and arm so that they can resist the forces of kickback.** Always use the auxiliary handle, if provided, for maximum control over kickback or the reaction of the torsional movement of the engine during starting. The operator can control the torsional movement and the kickback forces if the appropriate precautions are taken;
- b) **Never place your hand near the rotating attachment.**

The accessories may kick back in your hand;

- c) **Do not place your body in the area where the power tool can move if kickback (sudden recoil) occurs.**

This will propel the power tool in the opposite direction of disc movement at the point of engagement or binding;

- d) **Take special care when working on corners, sharp edges, among others. Avoid bouncing and jamming of the attachment.**

When working corners, sharp edges, or bouncing, can cause the attachment to jam and result in loss of control of the power tool or kickback (sudden recoil) of the power tool.

**⚠ WARNING** **Specific safety for grinding and cutting operations with abrasives**

- a) **Use only disc types that are recommended for the specific power tool and the specific tool holder that is designed for the selected disc.**

Discs that are not designed for the power tool cannot be properly protected and are unsafe;

- b) **The grinding surface of discs with a sunken center must be installed below the plane of the guard.**

An improperly installed disc may project burrs outside the plane of the guard and cannot be properly protected;

- c) **The guard must be securely fastened to the power tool and positioned to provide maximum safety, so that the least amount of the blade is exposed to the operator.**

Do not use damaged accessories. Before each use inspect the accessories. \* Check abrasive discs for damage.

- \* Check backing pads for cracks, tears or excessive wear

After inspecting and installing the accessory, operate the tool at maximum speed without charge for one minute.

Damaged accessories usually break during this period of time.

Do not use accessories that are not specifically designed and recommended by the manufacturer. The fact that the accessory may be installed on the power tool does not ensure safe operation.

- d) **Discs should be used only for their recommended applications. For example: do not grind with the side of a cut-off wheel.** Abrasive discs are used for perfect grinding. If lateral forces are applied, they can break;
- e) **Always use flanges in perfect condition, of the correct size according to the shape of the selected disk.**

A flange with the correct characteristics supports the disc, which reduces the possibility of disc rupture. The flanges for cut-off wheels can be different from the flanges for grinding wheels;

- f) **Do not use worn out disks from larger or higher capacity tools**

Disks that are designed for larger or higher capacity tools are not suitable for the increased speed that occurs in the operation of a smaller size or capacity tool and may defragment.

**⚠ WARNING** **Additional safety warnings for abrasive cutting operations**

- a) **Avoid locking or applying excessive pressure to the abrasive cut-off wheel.** Do not attempt to make an excessively deep cut.

Applying excessive force to the disc increases the load on the power tool and the susceptibility to deformation in the cutting area and increases the possibility of kickback (sudden recoil) or blade breakage;

- b) **Do not place your body in line and behind the rotating disc.**

When the disc, at the point of operation, is aligned with your body, the possibility of a kickback (sudden recoil) can propel the spinning disc and the power tool directly against you;

- c) **When disc operation is interrupted or cutting stops for any reason, turn off the power tool and keep it stationary until the disc comes to a complete stop.** Do not attempt to remove the blade while it is in motion, as this may cause kickback (sudden recoil) or similar effect.

Investigate and complete corrective actions to eliminate the cause of the spin interruption;

- d) **Do not restart the cutting operation on the workpiece. Allow the blade to reach maximum speed off the workpiece and carefully restart cutting.**

The abrasive cut-off disc can jam, move upwards or produce a kickback if cutting is restarted on the workpiece;

- e) **Support large workpieces on presses or clamping brackets to reduce the risk of the abrasive cut-off disc becoming trapped or of kickback (sudden recoil).**


Large pieces tend to sink under their own weight. Brackets should be placed under the workpiece near the cutting line and near the edge of the workpiece on both sides of the abrasive cut-off wheel;

- f) **Be careful when making a "very small cut" in walls or other blind areas or where there is no visibility of internal components.**

The protruding abrasive cutting disc can cut through gas or water pipes, electrical wiring, or objects that may cause kickback (sudden recoil).

# Parts


TRUPER®  
ERGO-PRO™



# Assembly


## Protection Guard Assembly

- Open the clamp lever and align the protruding parts inside the guard, push the guard down until the protruding parts engage and rotate freely with the corresponding slots in the shaft cover.
- With the clamp lever open, turn the guard to the desired working position.
- Fix pushing the clamp lever.




## Disc Assembly

- Fit the inner flange onto the axis.
  - Set the disc onto the inner flange.
  - Set the outer flange onto the axis.
    - Press the axis lock into the grinder head.
  - Screw the outer flange with the lock nut wrench until securely fastened.
- DANGER** The axis lock should only be used to change discs. Never use the axis lock to stop the disc while rotating.



## Auxiliary handle assembly

- For a safer operation use the auxiliary handle. Fit it into any of the three mounting orifices. Use the one that makes your job easier.



## Start Up

The angle grinder is a manual power tool used to grind and cut steel, pipes, iron angles, brick, tile, stone and / or ceramic pieces; to remove burr on metal surfaces, to level and make smooth welding lines.

## Switch On




- Connect the plug to the power inlet.
- Press the switch exactly in the pressing position (A), without releasing it, direct the pressure forward (B) and push down slightly, release the switch to remain locked.
- To stop operation, press in the pressing position (A) and then release the switch.

## How to correctly hold the tool

Always hold the tool with both hands. Hold the handle with one hand and the other hand hold the auxiliary handle. Be careful not to obstruct the ventilation slots.

• Grinding:  
For better results hold the tool 15° to 30° regarding the work piece. Move forwards to backwards applying light pressure with a constant rhythm. This way the work piece does not get too hot, will not discolor and there will not be rough edges.

• Cutting:  
Do not press, tilt or oscillate the tool. Work at a moderate speed. The disc should always rotate counterclockwise since there is a risk the tool shoots out uncontrolled.  
To cut hard stones using a diamond cutting disc is recommended.



## Useful tips

- Work placing the disc in the right position to prevent damage.
- Press the work piece applying pressure lower than the tool's weight to prevent overload damaging the motor and the disc.
- After installing a new disc allow it to run unloaded at least one minute. If vibration occurs replace immediately.

**CAUTION** • Avoid working on wood or soft metals like lead. These materials saturate the disc very quickly making it useless.

# Maintenance

**TRUPER®**  
**ERGO-PRO**

- Always disconnect the tool before cleaning.
- Never use water or other liquids. Use only a brush.
- To prevent the motor to overheat clean the ventilation slots regularly.
- Check all the tool components are perfectly fixed.
- The housing should not be cracked or damaged.
- Double-check the power cable is not cut or peeled.
- After a prolonged use the grease on the tool head should be replaced in a  **TRUPER®** Authorized Service Center.

## Repairs


Use only spare parts and accessories recommended by the manufacturer. In the event the tool is not working, repairs should be performed in a  **TRUPER®** Authorized Service Center

## Carbon brush replacement

- Carbon Brushes should be periodically checked and when worn, replaced always in a  **TRUPER®** Authorized Service Center.
- After replacing the carbon brushes request to inspect if the new carbon brushes can move freely in the carbon housing. Also request to run the tool 5 minutes to make even the contact with the carbon brushes and the commutator.
- Use only original  **TRUPER®** spare carbons specifically designed with the hardness and resistance adequate for each type of motor. Carbons that are out of specification could damage the motor.
- Both carbons should be changed simultaneous.
- For better results, it is recommended to use grinding and/or cutting disc to 4-1/2"  **TRUPER®**

## Storage

Neatly store the tool in a dry place and protected from dust and water.



# Authorized Service Centers

**TRUPER®  
ERGO-PRO**

In the event of any problem contacting a Truper Authorized Service Center, please see our webpage [www.truper.com](http://www.truper.com) to get an updated list, or call our toll-free numbers **800 690-6990** or **800 0187-8737** to get information about the nearest Service Center.

AGUASCALIENTES	<b>DE TODO PARA LA CONSTRUCCIÓN</b> GRAL. BARRAGÁN #1201, COL. GREMIAL, C.P. 20030, AGUASCALIENTES, AGS. TEL.: 449 994 0537	
BAJA CALIFORNIA	<b>SUCRASAL TIJUANA</b> AV. LA ENCANTADA, LOTE #5, PARQUE INDUSTRIAL EL FLORIDO II, C.P. 22244, TIJUANA, B.C. TEL.: 664 969 5100	
BAJA CALIFORNIA SUR	<b>FIX FERRETERÍAS</b> FELIPE ANGELES ESQ. RUIZ CORTÍNEZ S/N, COL. PUEBLO NUEVO, C.P. 23670, CD. CONSTITUCIÓN, B.C.S. TEL.: 613 132 1115	
CAMPECHE	<b>TORNILLERÍA Y FERRETERÍA AAA</b> AV. ÁLVARO OBREGÓN #524, COL. ESPERANZA C.P. 24080 CAMPECHE, CAMP. TEL.: 981 815 2808	
CHIAPAS	<b>FIX FERRETERÍAS</b> AV. CENTRAL SUR #27, COL. CENTRO, C.P. 30700, TAPACHULA, CHIS. TEL.: 962 118 4083	
CHIHUAHUA	<b>SUCRASAL CHIHUAHUA</b> AV. SILVESTRE TERRAZAS #12-111, PARQUE INDUSTRIAL BAFAR, CARRETERA MÉXICO CUAUHTÉMOC, C.P. 31415, CHIHUAHUA, CHIH. TEL. 614 434 0052	
MEXICO CITY	<b>FIX FERRETERÍAS</b> EL MONSTRUO DE CORREGIDORA, CORREGIDORA # 22, COL. CENTRO, C.P. 06606, CUAUHTÉMOC, CDMX. TEL: 55 5522 5031 / 5522 4861	
COAHUILA	<b>SUCRASAL TORREÓN</b> CALLE METAL MECÁNICA #280, PARQUE INDUSTRIAL ORIENTE, C.P. 27278, TORREÓN, COAH. TEL.: 871 209 6823	
COLIMA	<b>BOMBAS Y MOTORES BYMTESA DE MANZANILLO</b> BLVD. MIGUEL DE LA MADRID #190, COL. 16 DE SEPTIEMBRE, C.P. 28229, MANZANILLO, COL. TEL.: 314 332 1986 / 332 2013	
DURANGO	<b>TORNILLOS ÁGUILA, S.A. DE C.V.</b> MAZURIÓ #200, COL. LUIS ECHEVERRÍA, DURANGO, DGO.TEL.: 618 817 1946 / 618 818 2844	
ESTADO DE MÉXICO	<b>SUCRASAL CENTRO JILOTEPEC</b> PARQUE INDUSTRIAL 1, PARQUE INDUSTRIAL JILOTEPEC, JILOTEPEC, EDO. DE MÉX. C.P. 54257, TEL: 761 782 9101 EXT. 5728 Y 5102	
GUANAJUATO	<b>CÍA. FERRETERA NUEVO MUNDO S.A. DE C.V.</b> AV. MÉXICO - JAPÓN #225, CD. INDUSTRIAL, C.P. 38010, CELAAYA, GTO. TEL.: 461 617 7578 / 79 / 80 / 88	
GUERRERO	<b>CENTRO DE SERVICIO ECLIPSE</b> CALLE PRINCIPAL MZ.1 LT. 1, COL. SANTA FE, C.P. 39010, CHILPANCINGO, GRO. TEL: 747 478 5793	
HIDALGO	<b>FERREPRESOS S.A. DE C.V.</b> LIBERTAD ORIENTE #504 LOCAL 30, INTERIOR DE PASAJE ROBLEDO, COL. CENTRO, C.P. 43600, TULANCINGO, HGO. TEL.: 775 753 6615 / 775 753 6616	
JALISCO	<b>SUCRASAL GUADALAJARA</b> AV. ADOLFO B. HORN # 6800, COL: SANTA CRUZ DEL VALLE, C.P.: 45655, TLAJOMULCO DE ZÚÑIGA, JAL. TEL.: 33 3606 5285 AL 90	
MICHOACÁN	<b>FIX FERRETERÍAS</b> AV. PASEO DE LA REPÚBLICA #3140-A, COL. EX-HACIENDA DE LA HUERTA, C.P. 58050, MORELIA, MICH. TEL.: 443 334 6858	
MORELOS	<b>FIX FERRETERÍAS</b> CAPITÁN ANZURES #95, ESQ. JOSÉ PERDIZ, COL. CENTRO, C.P. 62740, CUAUTLA, MOR. TEL.: 735 352 8931	
NAYARIT	<b>HERRAMIENTAS DE TEPIC</b> MAZATLÁN #117, COL. CENTRO, C.P. 63000, TEPIC, NAY. TEL.: 311 258 0540	
NUEVO LEÓN	<b>SUCRASAL MONTERREY</b> CARRETERA LAREDO #300, 1B MONTERREY PARKS, COLONIA PUERTA DE ANÁHUAC, C.P. 66052, ESCOBEDO, NUEVO LEÓN, TEL.: 81 8352 8791 / 81 8352 8790	
OAXACA	<b>FIX FERRETERÍAS</b> AV. 20 DE NOVIEMBRE #910, COL. CENTRO, C.P. 68300, TUXTEPEC, OAX. TEL.: 287 106 3092	
PUEBLA	<b>SUCRASAL PUEBLA</b> AV. PERIFÉRICO #2-A, SAN LORENZO ALMECATLA, C.P. 72710, CUAUTLACINGO, PUE. TEL.: 222 282 8282 / 84 / 85 / 86	
QUERÉTARO	<b>ARU HERRAMIENTAS S.A. DE C.V.</b> AV. PUERTO DE VERACRUZ #110, COL. RANCHO DE ENMEDIO, C.P. 76842, SAN JUAN DEL RÍO, QRO. TEL.: 427 268 4544	
QUINTANA ROO	<b>FIX FERRETERÍAS</b> CARRETERA FEDERAL MZ. 46 LT. 3 LOCAL 2, COL. EJIDAL, C.P. 77710 PLAYA DEL CARMEN, Q.R. TEL.: 984 267 3140	
SAN LUIS POTOSÍ	<b>FIX FERRETERÍAS</b> AV. UNIVERSIDAD #1850, COL. EL PASEO, C.P. 78320, SAN LUIS POTOSÍ, S.L.P. TEL.: 444 822 4341	
SINALOA	<b>SUCRASAL CULIACÁN</b> AV. JESÚS KUMATE SUR #4301, COL. HACIENDA DE LA MORA, C.P. 80143, CULIACÁN, SIN. TEL.: 667 173 9139 / 173 8400	
SONORA	<b>FIX FERRETERÍAS</b> CALLE 5 DE FEBRERO #517, SUR LT. 25 MZ. 10, COL. CENTRO, C.P. 85000, CD. OBREGÓN, SON. TEL.: 644 413 2392	
TABASCO	<b>SUCRASAL VILLAHERMOSA</b> CALLE HELIO LOTES 1, 2 Y 3 MZ. #1, COL. INDUSTRIAL, 2A ETAPA, C.P. 86010, VILLAHERMOSA, TAB. TEL.: 993 353 7244	
TAMAULIPAS	<b>VM ORINGS Y REFACCIONES</b> CALLE ROSITA #527 ENTRE 20 DE NOVIEMBRE Y GRAL. RODRÍGUEZ, FRACC. REYNOSA, C.P. 88780, REYNOSA, TAMS. TEL.: 899 926 7552	
TLAXCALA	<b>SERVICIOS Y HERRAMIENTAS INDUSTRIALES</b> PABLO SIDAR #132, COL. BARROJO DE SAN BARTOLOMÉ, C.P. 90970, SAN PABLO DEL MONTE, TLAX. TEL.: 222 271 7502	
VERACRUZ	<b>LA CASA DISTRIBUIDORA TRUPER</b> BLVD. PRIMAVERA ESQ. HORTENSIA S/N, COL. PRIMAVERA C.P. 93308, POZA RICA, VER. TEL.: 782 823 8100 / 826 8484	
YUCATÁN	<b>SUCRASAL MÉRIDA</b> CALLE 33 #600 Y 602, LOCALIDAD ITZINCAB Y MULSAY, MIPI. UMÁN, C.P. 97390, MÉRIDA, YUC. TEL.: 999 912 2451	

**Code****Model****Brand**

100735

ERGO-4580-2

**TRUPER®**  
**ERGO-PRO**

This product is guaranteed for 2 years. To make the warranty valid or purchase parts and components you must present the product in Corregidora 22, Col. Centro, Alc. Cuauhtémoc, CDMX C.P. 06060 or at the establishment where you purchased it, or at any Truper® Service Center listed in the annex to the warranty policy and/or in [www.truper.com](http://www.truper.com). Transportation costs resulting from compliance of this warranty will be covered by  **TRUPER®**.

For questions or comments, call **800-690-6990**. Made in China. Imported by Truper S.A. de C.V. Parque Industrial 1, Parque Industrial Jilotepec, Jilotepec, Edo. de Méx. C.P. 54257

**2**  
YEARS

Stamp of the business. Date of purchase:

Sello del establecimiento comercial. Fecho de compra:

Este producto está garantizado por 2 años. Para hacer válida la garantía o adquirir piezas y componentes debiera presentar el producto en Corregidora 22, Col. Centro, Alc. Cuauhtémoc, CDMX C.P. 06060 o en el proveedor que lo adquirió. El establecimiento donde lo compre, o en algún Centro de Servicio Truper®, de los establecimientos que se detallan en el anexo de la polilla de garantía //o en [www.truper.com](http://www.truper.com). Los gastos de transporte que resulten para su cumplimiento se harán cargo por **TRUPER®**. Para dudas o comentarios, llame al **800-690-6990**. Hecho en China. Importado por Truper S.A. de C.V. Parque Industrial 1, Parque Industrial Jiutepec, Jiutepec, Edo. de Mex. C.P. 54257



Código	Modelo	Marca	ERGO-PRO	TRUPER®	ERGO-PRO	100735
					ERGO-4580-2	

**Poliza de Garantía**

**ERGO-PRO**  
**TRUPER®**

En caso de tener algún problema para contactar un Centro de Servicio Autorizado Truper®, consulte nuestra página [www.truper.com](http://www.truper.com) donde obtendrá una lista de actualizada, o llame al: **800 690-6990** ó **800 0187-8737** donde le informarán cuál es el Centro de Servicio más cercano.

MICHOACÁN  
FÍX FERRERIAS  
SUCURSAL GUADALAJARA  
JALISCO

TEL.: 33 3606 5285 AL 90  
VIAL DE LA REPÚBLICA #8800, COL. SANTA CRUZ DEL

TEL.: 33 3606 5285 AL 90  
HGO. TEL.: 775 753 6615 / 775 753 6616  
LIBRERIA RIBETE #54 LOCAL 30, INTERIOR DE PAISEL  
ROBLEDO, COL. CENTRO, C.P. 43600, TLAJUANCO, JAL.

HGO. TEL.: 775 753 6615 / 775 753 6616  
CHILPANCINGO, C.P. 43700, TEL.: 747 478 5793  
CENTRO DE SERVICIO ECLIPSE  
CALLE PRINCIPAL MZ. 1, LT. 1, COL. SANTA FE, C.P. 39301,

GUANAJAUTA  
AV. MEXICO - APDO. #225, C.D. INDUSTRIAL, C.P. 38100,

TEL.: 461 671 7578 / 79 / 80 / 88  
CELESTE, GTO. TEL.: 461 671 7578 / 79 / 80 / 88

MÉJICO  
ESTADO DE MÉJICO  
SUCURSAL CERTIRO JILOTEPEC  
PARQUE INDUSTRIAL JILOTEPEC

DGO. TEL.: 618 817 1946 / 618 818 2844  
MOLINO COLO. LUIS CECILIO DURANGO, DURANGO

TEL.: 314 352 1986 / 333 8013  
SINALOA  
SUCURSAL CHIACAHIN

TEL.: 667 175 1539 / 175 1540  
AV. JESÚS KINAME SUR #4501, COL. HACIENDA DELA

COLUMIA  
BVD. MIGUEL ELENA MARÍA #280, PARQUE INDUSTRIAL

TEL.: 871 209 66 25  
ORIENTE, C.P. 22280, TOLUCA, COAH.

COAHUILA  
SUCURSAL CERTIRO TRENCIN  
CALLE METAL MECANICA #280, PARQUE INDUSTRIAL

TEL.: 55 5522 5031 / 5522 4486  
COL. SILENTIA MIXEDO #128-11, PARQUE INDUSTRIAL

CHIHUAHUA  
SUCURSAL CHIHUAHUA  
CALLE AFRITRA MIXEDO #128-11, PARQUE INDUSTRIAL

TEL.: 66 434 0052  
CHIHUAHUA, CHIH. TEL.: 66 434 0052

CHIAPAS  
FÍX FERRERIAS  
AV. ALVARO OBREGÓN #27, COL. CENTRO, C.P. 30200,

CAMPACHE  
FÍX FERRERIAS  
C.P. 24080 CAMPECHE, CAMP. TEL.: 981 815 2808  
C.P. 24080 OBREGÓN #27, COL. SEPERANZA

BAJA  
FÍX FERRERIAS  
TEL.: 615 152 1115  
NEUVO, C.P. 23670, COL. CONSULTORIO, B.C.S.

CALIFORNIA SUR  
FÍX FERRERIAS  
TEL.: 66 496 5100  
FLOREDO II, C.P. 22244, TIJUANA, B.C.


CALIFORNIA  
SUCURSAL TIJUANA  
AV. LA ENCANTADA, LOTE #5, PARQUE INDUSTRIAL EL

AGUASCALIENTES  
DE TODO PARA LA CONSTRUCCIÓN  
C.RBL. BARRAGAN #1201, COL. GRIMAL, C.P. 20050,  
AGUASCALIENTES, AGS. TEL.: 449 994 0537

ESPAÑOL 12

**Centros de Servicio Autorizados**

VERACRUZ SUCURSAL MEDEIDA	TEL.: 909 227 752 CALLE 33 #600 Y 602, LOCALIDAD TIZCABY MULSAV, MPIO. MULSAV, C.P. 73390, MÉRIDA, YUC.
TAMAULIPAS WM FIXTURES Y EQUIPMENT	TEL.: 999 226 7552 CALLE ROSITA #527 ENTRE 20 DE NOVIEMBRE Y GRAL. RONDULE, P.R.C. ENCONSA, C.P. 88 800, REYNOSA, T.M.S., TEL.: 999 226 7552
TAMAULIPAS TABASCO SUCURSAL VILLAHERMOSA	TEL.: 993 353 7244 AV. ELEMPLA #86101, 1 Y 2 MZ #1, COL. INDUSTRIAL, TABASCO, C.P. 86101, VILLAHERMOSA, TAB.
SONORA SUCURSAL CHIACAHIN	TEL.: 644 413 2392 CALLE 6 DE FEBRERO #175, SUR, 1A MZ 10, COL. CENTRO, C.P. 85000, C.D. OREGON, SON.
SINALOA SUCURSAL CHIACAHIN	TEL.: 667 175 1539 / 175 1540 AV. JESÚS KINAME SUR #4501, COL. HACIENDA DELA
QUINTANA ROO FÍX FERRERIAS	TEL.: 984 267 5740 C.P. 77101 PLAZA DEL CARMEN, Q.R.
PUEBLA SUCURSAL PUEBLA	TEL.: 471 277 0544 AV. PRESIDENTE MÉNDEZ #6, 1A LOCAZ 2, COL. EJIDAL, PUEBLA, C.P. 78000, CDMX.
OAXACA SUCURSAL MONTERRÍE	TEL.: 222 28 282 / 84 / 85 / 86 AV. PRESIDENTE MÉNDEZ #910, COL. CENTRO, C.P. 68300, TUXTEPEC, OAX. TEL.: 28 106 5092
NAYARIT HERMOSILLAS DE TEPIC	TEL.: 311 251 9831 MAYILLAN #11, COL. CENTRO, C.P. 63000, TEPIC, NAY.
NUÉVO LEÓN SUCURSAL MONTERRÍE	TEL.: 222 28 282 / 84 / 85 / 86 CARRERILLA LARDO #500, 1B MONTERREY BRS, CULIACÁN, C.P. 60652, ESCOBEDO, COAH.
MORELOS FÍX FERRERIAS	TEL.: 753 352 8931 CALLE 111 AUTORIZAS #95, ESO. JOSE PEREZ, COL. CENTRO, C.P. 62240, CULIACÁN, MORELIA.
MICHOACÁN FÍX FERRERIAS	TEL.: 449 994 0537 CALLE 111 AUTORIZAS #95, ESO. JOSE PEREZ, COL. CENTRO, C.P. 62240, CULIACÁN, MORELIA.
GUANAJAUTA TORNILLOTS Y MOLDES RBTMESA DE MANZANILLO	TEL.: 871 209 66 25 CALLE 111 AUTORIZAS #18, 1A MZ 10, COL. EL PASO, C.P. 78320, SAN LUIS POTOSI, SLP, C.P. 78320.
COLIMA SUCURSAL CERTIRO RBTMESA DE MANZANILLO	TEL.: 314 352 1986 / 333 8013 AV. JESÚS KINAME SUR #4501, COL. HACIENDA DELA
DURANGO FÍX FERRERIAS	TEL.: 667 175 1539 / 175 1540 AV. JESÚS KINAME SUR #4501, COL. HACIENDA DELA
MÉJICO SUCURSAL CERTIRO JILOTEPEC	TEL.: 667 175 1539 / 175 1540 AV. JESÚS KINAME SUR #4501, COL. HACIENDA DELA
GUERRERO CENTRO DE SERVICIO ECLIPSE	TEL.: 447 478 5793 CALLE PRINCIPAL MZ. 1, LT. 1, COL. SANTA FE, C.P. 39301,
JALISCO FÍX FERRERIAS	TEL.: 461 671 7578 / 79 / 80 / 88 CELESTE, GTO. TEL.: 461 671 7578 / 79 / 80 / 88
JALISCO SUCURSAL GUADALAJARA	TEL.: 33 3606 5285 AL 90 VIAL DE LA REPÚBLICA #8800, COL. SANTA CRUZ DEL
MICHOCÁN FÍX FERRERIAS	TEL.: 443 344 6858 CALLE 111 AUTORIZAS #10, MEXICO, C.P. 58050, MORELIA.



Notas

ERGO-PRO<sup>®</sup>  
TRUPER

## Mantenimiento

polvo y agua

almacenarla en un lugar seco y protegida de

### Almacenamiento

- Para mejores resultados, se recomienda utilizar discos de corte y/o desbastar carbonas.
- Cuando se haga el cambio de carbonas siempre deban reemplazarse los de 4 1/2" (115 mm) marca TRUPER.
- Cuando se haga el cambio de carbonas nunca de específicas que dañen el motor.
- Solo se deben usar carbonas de repuesto originales **TRUPER**.
- Despues de usar carbonas de repuesto siempre enciendan la herramienta durante 5 minutos para emparafar el contacto de los numeros de carbonas nuevas e igualmente en el portacarbón y solicite que desgasifique.
- Los carbonas deben revisarse periódicamente, y ser reemplazados siempre por un Centro de Servicio Autorizado **TRUPER**.

### Cambio de carbonas




Utilice únicamente repuestos y accesorios recomendados por el fabricante. En caso de que la herramienta no funcione la reparación debe ser realizada por algún Centro de Servicio Autorizado **TRUPER**.

### Reparación

- Revise que todos los componentes de la herramienta estén bien fijos.
- La carcasa no debe estar curvada o dañada.
- Revise que la herramienta esté bien fija.
- Revise que la herramienta esté bien fija.
- Ponga el agua sobre el motor, debe limpiar las ranuras de ventilación del motor regularmente.
- Nunca utilice agua u otros líquidos, solamente utilice un cepillo.
- Descociente siempre la herramienta antes de proceder a limpiarla.

matriles saturan muy rápido el disco y lo hacen inservible.

- A AFIENCIÓN** • Evite trabajar sobre un disco nuevo o de plomo. Pues estos es casos de que el disco gire sin trabaja al menos un minuto.
- Despues de instalar un motor nuevo permita que el peso de la herramienta para evitar que se sobrecarga el disco.
- Presione sobre la pieza en la posición correcta para evitar que se dañe.
- Trabaje con el disco en la posición en la que el motor gira.



## Consejos útiles

- Corte: disco de corte de diamante.
- Para cortar piedras duras es recomendable usar un control.
- No presione, déjela oscilar la herramienta. Trabaje a una velocidad moderada.
- El disco debe girar siempre en sentido opuesto al movimiento de corte, nunca en el otro sentido. Puedes usar un ritmo constante. De esta forma la pieza de trabajo no se calienta demasiado, no se decolora y no se rompe.
- Para un mejor resultado sostenga la herramienta de 15° a 30° con respecto a la pieza de trabajo. Haga movimientos de adelante hacia atrás con una ligera vibración.
- Trabaje con una velocidad moderada.
- Nunca trabaje con una velocidad excesiva.
- Siempre sostenga la herramienta con ambas manos. Una mano sostiene el mango auxiliar y la otra el mango auxiliar.
- Trabaje con una velocidad moderada de no obstar las ranuras de ventilación.
- Siempre trabaje con una velocidad moderada de no obstar las ranuras de ventilación.
- Para interrumpir su funciónamiento, presione en la posición de apagado (A).
- Presione el interruptor exactamente en la posición de apagado (A), conecte la clavija al tomacorriente.
- Presione la pieza de la herramienta en la posición de apagado (B).
- Para interrumpir su funciónamiento, presione en la posición de apagado (B).


## Como sujetar adecuadamente la herramienta

- Coloque la herramienta en la posición de apagado (A) después de utilizarla.
- Para interrumpir su funciónamiento, presione en la posición de apagado (B).
- Si la pieza de la herramienta se calienta, deje que se enfrie antes de volver a utilizarla.
- Si la pieza de la herramienta se rompe, deje que se enfrie antes de volver a utilizarla.
- Si la pieza de la herramienta se rompe, deje que se enfrie antes de volver a utilizarla.

## Encendido

- La esmeriladora angular es una herramienta eléctrica manual, se utiliza para esmerilar y cortar acero, tubos, hierro en ángulo, latillas, azulejos, piedras y/o piezas de cerámica, para quitar la rebaba de las superficies de metal, para niveles y para limpiar los bordes.


## Puesta en marcha



## Montaje


## Montaje del mango auxiliar

- Para una operación segura utilice el mango auxiliar, coloque la pieza de apoyo de los tres orificios para montarla que le facilite más el trabajo.



- PELGRO** El seguirlo del eje solo se debe de utilizar para cambiar los discos. Nunca para frenar el disco mientras este grande.
4. Alineé la brida exterior con la llave de dos puntas hasta que quede bien fija.
  - Presione el seguro del eje en la abertura de la esmeriladora.
  3. Coloque el disco en la brida interior.
  2. Coloque el disco en la brida interior.
  1. Fije la brida interior en el eje.


### Montaje del disco



- Fije la empalme de la palanca de la abrazadera.
- Posición de trabajo deseada.
- Con la palanca de la abrazadera abierta, gire la guarda de protección hasta la posición de apertura de la abrazadera del eje.
- Abarca la palanca de la abrazadera y hace coincidir las partes sobresalientes del interior de la guarda de la abrazadera con las ranuras correspondientes de la guarda de la abrazadera del eje.

### Montaje de la guarda de protección

## Montaje






**Advertencias de Seguridad para uso de esmeriladoras**


**A ADVERTENCIA** No colocar un disco de sierra para traspaso en modos de uso alternativo. Tales cuchillas crean configuraciones (retroescobos bruscos) frecuentes y peligrosas de control.



seguidad, gusanos y manillar cuando opere



**Advertencias de Seguridad para uso de esmeriladora**



**A ADVERTENCIA** Nunca debe usar un disco cuyo diámetro sea mayor que el tamaño que le corresponda a la herramienta de corte. Los tres losas de las advertencias de seguridad que aparecen para el uso de sierra para traspaso se aplican a la herramienta eléctrica, incluidos los gusanos y los manillares.

**Ejemplo de disco apropiado**

**A ADVERTENCIA** Las chispas que produce la esmeriladora pueden resultar un peligro si no se toman las medidas adecuadas. Asegúrese de que no entre en contacto con la pieza de trabajo con una medida de apagado.

**A ADVERTENCIA** Nunca opere la herramienta inmersa en agua o en aceite. Nunca utilice la herramienta eléctrica cerca de materiales descometidaantes antes de revisar, ajustar o cambiar el disco.

**A ADVERTENCIA** Nunca opere la herramienta inmersa en agua o en aceite. Nunca toque el disco ni la pieza de trabajo con las manos. Nunca permita que la herramienta enagua se propague.

**A ADVERTENCIA** Nunca utilice la herramienta eléctrica para limpiar la pieza de trabajo. La herramienta enagua debe ser utilizada sólo para limpiar la pieza de trabajo.

**A ADVERTENCIA** Nunca utilice la herramienta eléctrica para limpiar la pieza de trabajo.

**A ADVERTENCIA** Nunca utilice la herramienta eléctrica para limpiar la pieza de trabajo.

**A ADVERTENCIA** Mantenga el cable de extensión por la herramienta. Nunca sostenga la herramienta por el cable de alimentación, sosteniéndola del otro lado del cable de alimentación.

**A ADVERTENCIA** Utilice lentes de seguridad para proteger los ojos de la extensión del cable de alimentación.

**A ADVERTENCIA** Utilice lentes de control de velocidad para proteger los ojos de la extensión del cable de alimentación.

**A ADVERTENCIA** Nunca utilice la herramienta de sierra para traspaso en modo de uso alternativo. Tales cuchillas crean configuraciones (retroescobos bruscos) frecuentes y peligrosas de control.

**Ejemplo de herramienta eléctrica más apropiada** Una herramienta eléctrica más apropiada es una sierra para traspaso que cumpla con las normas de seguridad establecidas en la legislación.

**ERGOD-PRO<sup>®</sup>**  
**TRUPER<sup>®</sup>**

con cumplimiento de la normativa de control de velocidad.

cuando se cumple la normativa de control de velocidad.

**Advertencias de Seguridad para uso de esmeriladora**

**A ADVERTENCIA** Nunca debe usar un disco cuyo diámetro sea mayor que el tamaño que le corresponda a la herramienta de corte. Los tres losas de las advertencias de seguridad que aparecen para el uso de sierra para traspaso se aplican a la herramienta eléctrica, incluidos los gusanos y los manillares.

**Ejemplo de disco apropiado**

comunidades donde se producen accidentes en el control de velocidad.

especialmente las que se producen en los países que tienen regulaciones y legislación más estricta.

en la legislación en vigor en su país.

**Ejemplo de disco apropiado** Una herramienta eléctrica más apropiada es una sierra para traspaso que cumple con la normativa de control de velocidad.

**A ADVERTENCIA** Nunca debe usar un disco cuyo diámetro sea menor que el tamaño que le corresponda a la herramienta de corte. Los tres losas de las advertencias de seguridad que aparecen para el uso de sierra para traspaso se aplican a la herramienta eléctrica, incluidos los gusanos y los manillares.

"encañidado" puede causar accidentes.

canocador hermanos eléctricas que tienen en interruptor en posición de

trabajando para renombrar la herramienta.

**Alimentación y/o a la Batería o Renombrar la herramienta.**

elite arrancadas accidentes. Asegúrese de que el interruptor



apropiadas, reduce el manejo significativa los daños personales.

zapatos y deslizantes, como los lentes de seguridad, mascarilla y ampliador.

E uso de equipo de seguridad como lentes de seguridad, mascarailla y ampliador.

use equipo de protección para los ojos.

Use equipo de seguridad. Use siempre protección para los ojos.

garser un daño personal.

Un momento de distracción mientras maneja el herramienta puede

causar daño a la salud o accidentes. No se si es salud o accidentes o

causas de la herramienta de drogas, alcohol o medicamentos.

Este altera, vigil lo que está haciendo y use el sentido común

seguridad Personal

E uso de un CFL reduce el riesgo de choque eléctrico.

de lámpara (CFL).

use una alimentación protegida por un interruptor de circuito

Si el uso de la herramienta en un lugar húmedo es inevitable,

eléctrico.

E uso de una extensión adecuada para exteriores reduce el riesgo de choque

extensión especial para uso en exteriores. Use una

Cuando maneje la herramienta en exteriores, use una

los cables dañados o rotos aumentan el riesgo de choque eléctrico.

los cables del calzón, corte, otras artílidas o piezas de movimiento.

levantar del cable la herramienta. Mantenga el cable

No fuercce el cable. Nunca use el cable para transportar.

E agua que ingresa en la herramienta aumenta el riesgo de choque eléctrico.

No use la herramienta a lluvia o condicones de humedad.

Hay un mayor riesgo de choque eléctrico si el cable pasa a tierra.

Este dispositivo, radiadores, condicones eléctricas y refrigeradores.

elite de control del cuerpo con superficies plásticas a tierra

choque eléctrico.

Chubas modifilas y accesorios diferentes aumentan el riesgo de

descarga eléctrica.

adaptable para dejarla de herramientas pulsadas a tierra.

La fuerza de trabajo una clavija. No use ningún tipo de

seguirá de la herramienta debe coincidir con el tornacorriente.

Seguridad eléctrica

Las distancias pueden hacer que pierda el control.

Mantenega alejados a los niños y curiosos cuando opera la

herramienta.

Las herramientas eléctricas producen chispas que encender

presencia de líquido, gas o polvo inflamables.

No maneje la herramienta en ambientes explosivos, como en

material inflamable.

Las herramientas eléctricas y accesorios son propensas a accidentes.

Las ideas desordenadas y obscuras son propensas a accidentes.

Mantenega el área de trabajo limpia y bien iluminada.

Area de trabajo

dado serio. Considera las advertencias y las instrucciones para futuras referencias.

entista a continuación. La misión de trabajar de ellas puede dar como resultado un choque eléctrico, incendio y/o

! ADVERTENCIA! Lea detenidamente todas las advertencias de seguridad y todas las instrucciones que se

! ADVERTENCIA! Lea detenidamente todas las advertencias de seguridad y todas las instrucciones que se

para mantener la herramienta en un Centro de Servicio Autorizado

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

para mantener la herramienta en un Centro de Servicio Autorizado.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

esta diseña para la herramienta para la mayoría de las aplicaciones diferentes.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

esta diseñada para la mayoría de las aplicaciones diferentes.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

multicortadoras son las más seguras en manos de las personas.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

partes móviles no están desalineadas o trabadas, que no

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

almacenamiento de los accesorios de cortes alfileres y limpias.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

descascante la herramienta de la fuerza suficiente de alimentación.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

no use la herramienta ni intentar no fundir.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

se usa el mimo para que lleve desechara.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

la herramienta adecuada hace un trabajo mejor cuando se usa correctamente.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

se usa el mimo para que lleve desechara.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

se usa el mimo para que lleve desechara.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

se usa el mimo para que lleve desechara.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

se usa el mimo para que lleve desechara.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

se usa el mimo para que lleve desechara.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

para herramientas generales de seguridad.

TRUEPER

usando solo Piezas de repuesto idénticas.

Servicio

ERGOC-PRO

AWG = Calibre de alambre estandarizado (American Wire Gauge). Referencia: NMX-J-195-ANCE

\* Se permite utilizarlo siempre cuando las extensiones mismas contienen con un aislante de protección contra sobrecorriente.

de 0 A hasta 11 A	18 AWG(•)	16 AWG	16 AWG	14 AWG	12 AWG	10 AWG	16 AWG(•)	16 AWG	14 AWG	12 AWG	10 AWG	8 AWG
de 11 A hasta 15 A	18 AWG(•)	16 AWG	16 AWG	14 AWG	12 AWG	10 AWG	16 AWG(•)	16 AWG	14 AWG	12 AWG	10 AWG	8 AWG
de 15 A hasta 23 A	18 AWG(•)	16 AWG	16 AWG	14 AWG	12 AWG	10 AWG	16 AWG(•)	16 AWG	14 AWG	12 AWG	10 AWG	8 AWG
de 23 A hasta 30 A	18 AWG(•)	16 AWG	16 AWG	14 AWG	12 AWG	10 AWG	16 AWG(•)	16 AWG	14 AWG	12 AWG	10 AWG	8 AWG
de 30 A hasta 40 A	18 AWG(•)	16 AWG	16 AWG	14 AWG	12 AWG	10 AWG	16 AWG(•)	16 AWG	14 AWG	12 AWG	10 AWG	8 AWG

## Capacidad en Ampères


Número de  
conductores

de 1,8 m a 15 m | mayor de 15 m

Calibre de extensión

Al usar un cable de extensión, asegúrese de usar el calibre suficiente para transportar la corriente que consumirá su herramienta. Un cable de extensión inferior o ocasionalmente causará la transición en la línea, teniendo como resultado pérdida de potencia y sobrecalefacción del motor. Si gigue tiene el cable de la capacidad de amperes indicada en la placa de datos de la herramienta. Si tiene dudas use el longitud del cable y de la herramienta.

## ADVERTENCIA



Las herramientas de doble aislamiento y aislamiento reforzado iluminan la necesidad de conectar el cable de conexión de las partes con conexión a tierra.

Conexión a tierra o de un sistema de conexión eléctrica con conexión a tierra.

Al usar una herramienta de doble aislamiento y aislamiento reforzado iluminan la necesidad de conectar el cable de conexión de las terminales, todos los circuitos de alimentación deben ser desconectados.

## ADVERTENCIA

Autoizado **TRUEPER**, con el fin de evitar algún riesgo de este hardware por separado o derriñamiento de líquidos durante su operación. No lo expone a líquidos y/o humedad.

La construcción de instrumentos de este tipo es más resistente y duradera que la de instrumentos de tipo convencional.

Si el cable de alimentación se daña, este debe ser reemplazado por el fabricante o Centro de Servicio

## ADVERTENCIA

La clase de aislamiento térmico de los demandas del motor: Clase H

La base de construcción térmica supera las demandas del motor.


El cable de alimentación tiene sujetacables tipo Y

Código •	100735	Descripción •	Esmeriladora angular
DISCOS •	4 1/2" (115 mm)	Tensión •	220 V ~
FRECUENCIA •	50 Hz / 60 Hz	Corriente •	3,6 A
POTENCIAS •	850 W	Velocidad •	12 000 r/min
CICLO DE TRABAJO •	30 minutos de trabajo por 15 minutos de descanso. Máximo 3 horas diarias.	CONDUCTORES •	H05VV-F 2 x 0,75 mm <sup>2</sup>
ALISAMIENTO •	La base de construcción térmica supera las demandas del motor.	CLASE DE AISLAMIENTO •	Grado IP 2

ERGO-4580-2

ERGO-PRO<sup>®</sup>  
TRUEPER<sup>®</sup>

Especificaciones técnicas



ERGO-4580-2

Para poder sacar el máximo provecho de la herramienta, alargar su vida útil, hacer válida la garantía en caso de ser necesario y evitar riesgos o lesiones graves, es fundamental leer este instructivo por completo antes de usar la herramienta.

Guarde este instructivo para futuras referencias. Los gráficos de este instructivo son para referencia, pueden variar del aspecto real de la herramienta.

## ATENCIÓN

## Indice

- |    |                                     |
|----|-------------------------------------|
| 12 | Póliza de Garantía                  |
| 11 | Centros de Servicio Autorizados     |
| 10 | Notas                               |
| 9  | Mantenimiento                       |
| 8  | Puesta en marcha                    |
| 7  | Montaje                             |
| 7  | Partes                              |
| 5  | Advertencias de Seguridad           |
| 4  | Advertencias generales de Seguridad |
| 3  | Requerimientos eléctricos           |
| 3  | Especificaciones técnicas           |

**ERGO-PRO**  
**TRUPER®**



Lea este instructivo por completo  
antes de usar la herramienta.

**ATENCIÓN**



# ERGO-4580-2


Modelo ERGO-4580-2  
Código 100735

Este instructivo es para:

850 W  
 $4\frac{1}{2}$ "  
115 mm  
Diámetro  
Potencia

## Esmerrilladora angular

Instructivo de



**ERGO-PRO**  
**TRUPER®**

ESPAÑOL  
ENGLISH