

INSTRUCTIVE


Cordless impact wrench

13 mm
20 V... 1/2"
Drive

LIMI-20P

Applies for:

Code	Model
28268	LIMI-20P



CAUTION



Read this manual thoroughly
before using the tool.



Technical data	3
Power requirements	3
 General safety requirements for electric tools	4
 Safety warnings for the use of cordless impact wrenches	5
Parts	6
Startup	6
Troubleshooting	9
Maintenance	9
Environmental protection	9
Notes	10
Authorized service centers	11
Warranty policy	12

CAUTION

To get the most out of the tool, extend its lifespan, claim the warranty if necessary, and avoid serious risks or injuries, it is essential to read this manual in its entirety before using the tool.

The illustrations in this manual are for reference only and may differ from the real appearance of the tool.

Usage and care recommendations

 Charge the battery only with the included charger or its equivalent specified by TRUPER.

 Follow the battery usage considerations (page 7).

 Keep the ventilation openings of the tool and charger clean.

LIMI-20P

Code •	28268
Description •	Cordless impact wrench
Drive •	1/2"
Voltage •	20 V---
Speed •	0 RPM - 2 200 RPM
Strokes per minute •	0 beats/min - 3 000 beats/min (BPM)
Rotation •	forward- reverse
IP rating •	IP 20
Maximum Torque •	155 lb-ft (210 Nm)
Battery •	Lithium-ion 20 V--- 4 Ah Charging time: about 120 minutes
Charger •	Input: Voltage: 127 V~ Frequency: 60 Hz Input current: 0.9 A Output: 21 V--- 2.5 A

The power cable has Y-type cable holders. The tool's construction class is Class III.

The charger's construction class is Reinforced Insulation.



If the power cable is damaged, it must be replaced by the manufacturer or a TRUPER Authorized Service Center to prevent any risk of electric shock or significant accidents. The electrical insulation of this tool is altered by splashes or spillage of liquids during its operation.

Do not expose it to rain, liquids, and/or moisture.




Before accessing the terminals, all power circuits must be disconnected.



Electric requirements

⚠ WARNING Tools with double insulation and reinforced insulation are equipped with a polarized plug (one prong is wider than the other). This plug fits into any polarized outlet and can only be connected in one way. If the plug does not fit into the outlet, turn it over. If it still does not fit, contact a qualified electrician, or install a polarized outlet. Do not alter the plug in any way. Double-insulated and reinforced insulation tools eliminate the need for a 3-wire grounded power cord or a grounded electrical system.



⚠ WARNING When using an extension cord, ensure to use a gauge to carry the current that the tool will consume. A lower gauge cord will cause voltage drops in the line, resulting in power loss and motor overheating. The following table shows the correct size to be used depending on the cable length and the amperage capacity indicated on the tool's data plate. If in doubt, use the next higher gauge.

Capacity in Amperes	Number of conductors	Extension gauge	
		From 1.8 m to 15 m	Higher than 15 m
From 0 A to 10 A	3 (one to ground)	18 AWG(*)	16 AWG
From 10 A to 13 A		16 AWG	14 AWG
From 13 A to 15 A		14 AWG	12 AWG
From 15 A to 20 A		8 AWG	6 AWG

* It is allowed to use it if the extensions themselves have an overcurrent protection device.

AWG = American Wire Gauge. Reference: NMX-J-195-ANCE.

⚠ WARNING When operating electric tools outdoors, use a grounded extension cord marked as VOLTECK 'Outdoor Use'. These extensions are specially designed for outdoor use and reduce the risk of electric shock.



⚠ WARNING. Read all safety warnings and all instructions listed below carefully. Failure to follow any of them may result in electric shock, fire, and/or serious injury. Keep the warnings and instructions for future reference.

Work area**Keep the work area clean and well-lit.**

Cluttered and dim areas can lead to accidents.

**Do not operate the tool in explosive atmospheres, as in the presence of flammable liquids, gas, or dust.**

The electric tools produce sparks that can ignite flammable material.

Keep children and other individuals at a safe distance while using the equipment.

Distractions can cause loss of control and lead to accidents.

Electrical safety**The tool plug must match the outlet.****Never modify the plug in any way.**

Do not use any type of adapter with grounded electrical tools.

Unmodified electrical tools and matching plugs will reduce the risk of electric shock.

Avoid bodily contact with grounded surfaces, such as pipes, radiators, stoves, and refrigerators.

There is an increased risk of electric shock if your body is grounded.

Water entering an electrical tool will increase the risk of electric shock.

The entry of water into an electrical tool will increase the risk of electric shock.

Do not force the cable. Never use the cable for carrying, lifting, or disconnecting the tool. Keep the cable away from heat, oil, sharp edges, or moving parts.

Damaged or tangled cables increase the risk of electric shock.

When operating an electrical tool outdoors, use an extension cord suitable for outdoor use.

The use of a suitable outdoor rated cable reduces the risk of electric shock.

If it is unavoidable to operate the tool in a damp location, use a power source protected by a ground fault circuit interrupter (GFCI).

The use of a GFCI reduces the risk of electric shock.

Personal safety**Stay alert, watch what you are doing, and use common sense when handling a tool. Do not use it if you are tired or under the influence of drugs, alcohol, or medication.**

A moment of distraction while handling the tool can cause personal injury.

Use safety equipment. Always wear eye protection.

The use of safety equipment such as safety glasses, dust mask, slip-resistant shoes, helmet, and ear protection in appropriate conditions significantly reduces the risk of personal injury.

**Avoid accidental starts. Ensure the switch is in the "off" position before connecting to the power source and/or battery or transporting the tool.**

Carrying power tools with your finger on the switch or connecting tools with the switch in the "on" position can cause accidents.

Remove any wrenches or adjusting tool before starting the power tool.

Wrenches or tools left on the rotating parts of the tool can cause personal injury.

Do not exceed your range of motion. Keep both feet firmly planted on the ground and maintain balance.

This allows better control of the tool in unexpected situations.

Dress appropriately. Do not wear loose clothing or jewelry. Keep your hair, clothing, and gloves away from moving parts.

Loose clothes, jewelry, or long hair can get caught in moving parts.

If dust extraction and collection devices are available for the tool, check their connections and use them correctly.

The use of these devices reduces risks associated with dust.

Tool use and care**Do not force the tool. Use the appropriate tool for the task at hand.**

The right tool performs better and is safer when used at the intended pace.

Do not use the tool if the switch is not functioning.

Any power tool that cannot be turned on or off is dangerous and must be repaired before operation.

Disconnect the tool from the power source and/or battery before making any adjustments, changing accessories, or storing it.

These measures reduce the risk of an accidental start of the tool.

**Store the tools out of the reach of children and do not allow them to be handled by individuals unfamiliar with the tools or their instructions.**

Power tools are dangerous in untrained hands.

**Maintain the tool. Ensure that the moving parts are not misaligned or jammed, and that there are no broken parts or other conditions that may affect its operation. Repair any damage before using the tool.**

Many accidents are caused by inadequate tool maintenance.

Keep cutting accessories sharp and clean.

Well-maintained cutting accessories are less likely to jam and easier to control.

Use the tool, its components, and accessories in accordance with these instructions and as intended for the type of tool, in appropriate working conditions.

Using the tool for applications other than those for which it is designed could cause a hazardous situation.

Service**Repair the tool at a TRUPER Authorized Service Center using only identical replacements parts.**

This will maintain the safety of the tool.

Use and care of the battery-powered tool**Only recharge with the charger specified by PRETUL®.**

The charger included with the machine may pose a fire hazard if used with another battery.

**Use batteries specifically designed for the tool.**

The use of any other battery may pose a risk of damage and fire.

When battery pack is not in use, keep it away from other metal objects, like paper clips, coins, keys, nails, screws, or other small metal objects, that can make a connection from one terminal to another.

Short-circuiting between battery terminals can cause burns or fire.

In abusive conditions, battery liquid may be expelled; avoid contact. If there is accidental contact, rinse with water. If the liquid meets the eyes, seek medical assistance.

The expelled liquid can cause irritation or burns.



This tool is in compliance with the Official Mexican Standard (NOM - Norma Oficial Mexicana).

General safety warnings

for the use of cordless impact wrenches

PRETUL®

Batteries and charger

DANGER • Use only the included PRETUL charger for the battery of the tool. Other batteries may pose risks of injury or fire.

DANGER • Use only batteries designed specifically for the tool. Other batteries may pose risks of injury or fire.
• Connect the charger only to an alternating current (AC) power supply.

DANGER • Do not use the charger outdoors.

- Respect the "+/-" polarity when charging.
- Never recharge a leaking battery.
- Do not use batteries or the charger for purposes other than those they were designed for.
- Do not modify the battery or charger contacts.
- Do not expose the battery pack to temperatures above 122 °F (50°C)

DANGER • Never expose batteries to fire; they could explode.

CAUTION • Keep batteries away from any metallic objects such as clips, coins, keys, nails, screws, or any other object that could cause the terminals to make contact, this could lead to a short circuit that may cause burns or fires.

CAUTION • Under extreme conditions, battery liquid may spill. If this happens, avoid any contact. In case of accidental contact, wash with plenty of water, rinse with lemon juice and vinegar. If the liquid meets the eyes, wash with plenty of water for several minutes and seek immediate medical help. The expelled liquid from the batteries could cause irritation or burns.

CAUTION • To maximize the battery lifespan, make sure to discharge it fully at least once a month. Avoid keeping the battery without charging for more than three months, and always ensure it reaches its full capacity during charging. Before the initial use of the machine, charge the battery for a minimum of 3 hours.
• Avoid frequent interruptions while screwing to prevent potential damage to the battery.

Choose the appropriate accessory

CAUTION • Select the correct socket for the material you're working on to minimize the risk of severe injuries and speed up the work.
• Avoid using sockets that surpass the capacity of the tool's drive.
• Use only impact sockets.

Before operating the tool

• Take the necessary time to evaluate the task and ensure all safety precautions are observed before starting to work.
• Adjust the accessory correctly.

DANGER • Ensure the switch is in the OFF position before inserting the battery; otherwise, it may unexpectedly start, posing a risk of serious injury.
• If the tool is equipped with auxiliary handles, use them. Loss of control can lead to personal injuries.

When operating the impact wrench

CAUTION • This tool is designed to work with sockets. IT IS NOT A DRILL.

- This is a light-duty tool, do not use it for removing or installing screws that require high torque.
- Do not modify the tool or its accessories in any way.
- Turn on the impact wrench after placing the sockets.
- Do not apply excessive force.
- Do not use this tool with one hand.
- After each use, remove the sockets and extensions and store them properly.

WARNING • CHOKING HAZARD! Children can swallow small parts and choke.
• Keep small parts away from children.




Hold the power tool by the insulated grip surfaces when performing an operation where the fastener may meet hidden wires or its own power cable.

Fasteners that meet an energized wire can turn the metallic parts of the power tool into live components, resulting in an electric shock for the operator.

- Use ear protections when performing services with 85dB noise exceed. Prolonged exposure to noise can cause hearing loss.
- Use a dust mask and dust extraction equipment if necessary. Remember that working with materials such as asbestos, lead-based paints, additives, certain types of wood, metals, or minerals can be highly toxic.
- Use safety glasses.






Start up

Battery charge

- Connect the charger plug to a 127 V~ outlet (the green light on the charge indicator will turn on).
- Insert the battery into the charger by sliding it as shown in the picture. The green light will turn off, and the red light should turn on, indicating that it is already charging.
- When the battery is fully charged, the green light will turn on, and the red light will turn off.
- Disconnect the charger from the power once the charging is complete.
- If the red-light flashes, it indicates that the battery temperature is 32 °F (0 °C) or above 113 °F (45 °C). Wait until the battery temperature is within the appropriate range before charging.
- If the battery indicator lights do not turn on after inserting the battery into the charger, it indicates that the battery is defective. Please replace the battery with a new one.




Considerations for battery use

The battery is shipped in a DISCHARGED state by default. It is necessary to charge it for approximately 1 hour and 30 minutes before use.

The normal charging temperature range is from 32 °F (0 °C) or above 113 °F (45 °C). Charging is automatically suspended outside this range until it reaches the correct temperature. The normal discharge/working temperature range is from 32 °F (0 °C) or above 167 °F (75 °C). If the temperature exceeds 167 °F (75 °C) the electronic control will shut off power until the tool reaches the optimal temperature range. If the battery voltage drops below the normal level during operation, the tool will stop functioning. Between each charge, allow the charger a 15-minute rest. In a warm environment or after prolonged use, the battery may become too hot to recharge. Allow the battery to cool down before attempting to recharge it.

Installing and removing the battery

- To install the battery in the tool handle, align the battery unit with the rails inside the tool handle and slide it into the handle until the battery unit is firmly inserted into the tool; verify it does not come out on its own.
- To remove the battery, press the release button (**C**) and firmly pull the battery to remove it from the tool handle.



The charger has 2 LED indicators that show the charging process status.	Red LED status	Green LED status	Charger status
	Off	Off	No battery
	Off	On	There is no battery inserted or it has been inserted but charging is completed.
	On	Off	Battery charging

Socket installation


- Ensure the machine is off, set the direction button to the lock position (center).
- Take the socket and firmly push it onto the drive. The retaining ring compresses to allow the accessory to slide on top. Once the accessory is installed, the retaining ring applies pressure to help the accessory's retaining.

Removing the accessory

- To remove an accessory, turn off the machine, hold the accessory, and pull it firmly.
- Always use impact sockets for this tool. Do not use hand tool sockets. Check the **PRETUL** catalog to explore our variety of accessories.
- Use 1/2" (13 mm) drive sockets.
- Adapters for different sizes sockets are not recommended; use them only if strictly necessary.
- If the socket has holes, always use rubber rings and steel pins when placing it on the drive.
- If the drive has a retaining ring, verify that it is in good condition, and if it is damaged, replace it immediately.

⚠ WARNING • If a socket has not been secured and adjusted as instructed, it can be ejected and cause injury to the operator.

⚠ WARNING • The use of non-impact accessories can lead to breakages and hazardous situations. Inspect the accessory before use to ensure the absence of cracks.




Rotation direction

- To screw, release the switch and press the rotation direction button on the side indicated by the marks.
- To reverse and unscrew, press it on the opposite side.
- The tool switch locks if the rotation direction button is in the middle position.

⚠ CAUTION • The first time you turn on the tool after reversing rotation, you may hear a "click." This is normal and does not represent any problem.

⚠ CAUTION • To prevent damage to the tool, never reverse the rotation direction while the tool is in operation.




Belt clip

- The belt clip can be assembled on either side of the tool using only the provided screw, making it suitable for left or right-handed users.
- If you want to move the belt clip to the other side, remove the screw holding the belt clip in place and reassemble it on the other side. Ensure the screw is securely tightened.
- If you never need the clip, you can remove it from the tool.

Power On and operation control

- Press the switch to start operation; release the switch to stop operation.
- The switch allows you to select the appropriate speed for each task. The tighter you press the switch, the faster the tool will operate.
- When releasing the on/off switch, the machine will stop.
- Move the direction button to the middle position to lock the on/off switch.



Screwing - unscrewing

Consider the following points as the torque may be affected by each of them:

- **Voltage:** Insufficient voltage from a nearly discharged battery or cell will reduce the torque.
- **Accessory size:** Using an incorrect accessory size may result in a reduced torque.
- **Bolt size:** Larger diameter bolts generally require higher tightening torque. The tightening torque also varies based on length, grade, and torsion coefficient.
- **Bolt:** Ensure all threads are free of rust and other debris to facilitate proper torque.
- **Material:** The type of material and surface finish may affect the torque.
- **Tightening time:** Longer tightening time increases the torque. A tightening time greater than recommended could put too much tension on fasteners or cause them to strip or become damaged.

Troubleshooting

PRETUL

Problem	Cause	Corrective action
The tool loses efficiency.	<ul style="list-style-type: none">Low battery.	<ul style="list-style-type: none">Charge the battery.
The trigger cannot be pressed.	<ul style="list-style-type: none">The rotation direction button is in the lock position.	<ul style="list-style-type: none">Move the rotation direction button to forward or reverse position.
The trigger can be pressed but the tool does not rotate.	<ul style="list-style-type: none">Battery discharged.	<ul style="list-style-type: none">Charge the battery.
The battery leaks.	<ul style="list-style-type: none">Minor dripping may occur in extreme temperatures or after heavy use; this is normal.Intense or very noticeable dripping is due to a damaged battery.	<ul style="list-style-type: none">Clean the liquid from the skin or clothing immediately with water and soap.Replace the battery immediately.
The battery does not charge, and the charger light does not turn on.	<ul style="list-style-type: none">Battery improperly placed in the charger.Charger improperly connected to the electrical outlet.	<ul style="list-style-type: none">Correctly insert the battery into the charger.Check that the plug is properly connected to the outlet.
The tool heats up after prolonged periods of work.	<ul style="list-style-type: none">Normal heating due to energy absorption from the motor gears and electricity during work.	<ul style="list-style-type: none">Let the tool cool down for a period of 5 minutes.
The battery heats up during operation.	<ul style="list-style-type: none">Normal heating due to energy extracted from the battery while the tool is in operation.	<ul style="list-style-type: none">Stop the tool for a period of 5 minutes to let the battery cool down.
The battery heats up during charging.	<ul style="list-style-type: none">Normal heating due to chemical reactions inside the battery during charging.	
The charger heats up during charging.	<ul style="list-style-type: none">Normal heating due to voltage regulation.	

Maintenance

Cleaning and care


- Make sure proper cooling of the motor by keeping vents clean and unblocked.
- Regularly inspect all mounting screws and ensure they are properly tightened. If any screws are loose, tighten them immediately.
- Clean the tool with a clean and soft cloth. Do not use alcohol or detergent. Disconnect the tool and remove the battery before cleaning.

Service

Tool service must be performed exclusively at a TRUPER Authorized Service Center. Service and maintenance carried out by unqualified individuals can be dangerous, potentially causing personal harm, and may also void the product warranty.

Environmental protection

Electrical appliances and batteries must not be disposed off with household waste. Please deliver this appliance, as well as its batteries, with the contacts insulated with adhesive tapes to a recycling center. Check the location of the nearest center in your community.



Authorized service centers

PRETUL®

If you have any problems contacting a TRUPER Authorized Service Center, please consult our webpage WWW.TRUPER.COM to get an updated list, or call our toll-free numbers **800 690-6990** or **800-018-7873** to get information about the nearest Service Center.

AGUASCALIENTES	DE TODO PARA LA CONSTRUCCIÓN GRAL. BARRAGÁN #1201, COL. GREMIAL, C.P. 20030, AGUASCALIENTES, AGS. TEL.: 449 994 0537	MORELOS	FIX FERRETERÍAS CAPITÁN ANZURES #95, ESQ. JOSÉ PERDIZ, COL. CENTRO, C.P. 62740, CUATLA, MOR. TEL.: 735 352 893
BAJA CALIFORNIA	SUCURSAL TIJUANA AV. LA ENCANTADA, LOTE #5, PARQUE INDUSTRIAL EL FLORIDO II, C.P. 22244, TIJUANA, B.C. TEL.: 664 969 5100	NAYARIT	HERRAMIENTAS DE TEPIC MAZATLÁN #117, COL. CENTRO, C.P. 63000, TEPIC, NAY. TEL.: 311 258 0540
BAJA CALIFORNIA SUR	FIX FERRETERÍAS FELIPE ÁNGELES ESQ. RUIZ CORTÍNEZ S/N, COL. PUEBLO NUENO, C.P. 23670, CD. CONSTITUCIÓN, B.C.S. TEL.: 613 132 1115	NUEVO LEÓN	SUCURSAL MONTERREY CARRETERA LAREDO #300, 1B MONTERREY PARKS, COLONIA PUERTA DE ANÁHUAC, C.P. 66052, ESCOBEDO, NUEVO LEÓN, TEL.: 81 8352 8791 / 81 8352 8790
CAMPECHE	TORNILLERÍA Y FERRETERÍA AAA AV. ALVARO OBREGÓN #324, COL. ESPERANZA C.P. 24080 CAMPECHE, CAMP. TEL.: 981 815 2808	OAXACA	FIX FERRETERÍAS AV. 20 DE NOVIEMBRE #910, COL. CENTRO, C.P. 68300, TUXTEPEC, OAX. TEL.: 287 106 3092
CHIAPAS	FIX FERRETERÍAS AV. CENTRAL SUR #27, COL. CENTRO, C.P. 30700, TAPACHULA, CHIS. TEL.: 962 118 4083	PUEBLA	SUCURSAL PUEBLA AV. PERIFÉRICO #2-A, SAN LORENZO ALMECATLA, C.P. 72710, CUAUTLACINGO, PUE. TEL.: 222 282 8282 / 84 / 85 / 86
CHIHUAHUA	SUCURSAL CHIHUAHUA AV. SILVESTER TERRAZAS #128-11, PARQUE INDUSTRIAL BAFAR, CARRETERA MÉXICO CUAUHTEMOC, C.P. 31415, CHIHUAHUA, CHIH. TEL. 614 434 0052	QUERÉTARO	ARU HERRAMIENTAS S.A DE C.V. AV. PUERTO DE VERACRUZ #110, COL. RANCHO DE ENMEDIO, C.P. 76842, SAN JUAN DEL RÍO, QRO. TEL.: 427 268 4544
Ciudad de MÉXICO	FIX FERRETERÍAS EL MONSTRUO DE CORREDORA, CORREDORA # 35, COL. CENTRO, C.P. 06060, CUAUHTEMOC, CDMX. TEL: 55 5522 5031 / 5522 4861	QUINTANA ROO	FIX FERRETERÍAS CARRETERA FEDERAL MZ. 46 LT. 3 LOCAL 2, COL. EJIDAL, C.P. 77110 PLATA DEL CARMEN, Q.R. TEL.: 984 267 3140
COAHUILA	SUCURSAL TORRÉON CALLE METAL MECÁNICA #280, PARQUE INDUSTRIAL ORIENTE, C.P. 27278, TORRÉON, COAH. TEL.: 871 209 68 23	SAN LUIS POTOSÍ	FIX FERRETERÍAS AV. UNIVERSIDAD #1850, COL. EL PASEO, C.P. 78320, SAN LUIS POTOSÍ, SLP. TEL.: 444 822 4341
COLIMA	BOMBAS Y MOTORES BYMTESA DE MANZANILLO BLVD. MIGUEL DE LA MADRID #190, COL. 16 DE SEPTIEMBRE, C.P. 28239, MANZANILLO, COL. TEL.: 314 332 1986 / 332 8013	SINALOA	SUCURSAL CULIACÁN AV. JESÚS KUMATE #4301, COL. HACIENDA DE LA MORA, C.P. 80143, CULIACÁN, SIN. TEL.: 667 173 9139 / 173 8400
DURANGO	TORNILLOS ÁGUILA, S.A. DE C.V. MAZURIÓ #200, COL. LUIS ECHEVERRÍA, DURANGO, DGO.TEL.: 618 817 1946 / 618 818 2844	SONORA	FIX FERRETERÍAS CALLE 5 DE FEBRERO #517, SUR LT. 25 MZ. 10, COL. CENTRO, C.P. 85000, CD. OBREGÓN, SON. TEL.: 644 413 2392
ESTADO DE MÉXICO	SUCURSAL CENTRO JILOTEPEC PARQUE INDUSTRIAL # 1, COL. PARQUE INDUSTRIAL JILOTEPEC, JILOTEPEC, EDO. DE MÉX. C.P. 54257 TEL: 761 782 9101 EXT. 5728 y 5102	TABASCO	SUCURSAL VILLAHERMOSA CALLE HELIO LOTES 1, 2 Y 3 MZ. #1, COL. INDUSTRIAL, 2A ETAPA, C.P. 86010, VILLAHERMOSA, TAB. TEL.: 993 355 7244
GUANAJUATO	CIA. FERRETERA NUEVO MUNDO S.A. DE C.V. AV. MÉXICO - JAPÓN #225, CD. INDUSTRIAL, C.P. 38010, CELAYA, GTO. TEL.: 461 617 7578 / 79 / 80 / 88	TAMAULIPAS	VM ORINGS Y REFACCIONES CALLE ROSITA #527 ENTRE 20 DE NOVIEMBRE Y GRAL. RODRÍGUEZ, FRACC. REYNOSA, C.P. 88780, REYNOSA, TAMS. TEL.: 899 926 7552
GUERRERO	CENTRO DE SERVICIO ECLIPSE CALLE PRINCIPAL MZ1 LT. 1, COL. SANTA FE, C.P. 39010, CHILPANCINGO, GRO. TEL.: 747 478 5795	TLAXCALA	SERVICIOS Y HERRAMIENTAS INDUSTRIALES PABLO SIDAR #132, COL. BARRIO DE SAN BARTOLOMÉ, C.P. 90070, SAN PABLO DEL MONTE, TLAX. TEL.: 222 271 7502
HIDALGO	FERREPRECIOS S.A. DE C.V. LIBERTAD ORIENTE #304 LOCAL 30, INTERIOR DE PASAJE ROBLEDO, COL. CENTRO, C.P. 43600, TULANCINGO, HGO. TEL.: 775 753 6615 / 775 753 6616	VERACRUZ	LA CASA DISTRIBUIDORA TRUPER BLVD. PRIMAVERA, ESQ. HORTENSIA S/N, COL. PRIMAVERA C.P. 93508, POZA RICA, VER. TEL.: 782 823 8100 / 826 8484
JALISCO	SUCURSAL GUADALAJARA AV. ADOLFO B. HORN #6800, COL: SANTA CRUZ DEL VALLE, C.P.: 45655, TLAJOMULCO DE ZÚÑIGA, JAL. TEL.: 33 3606 5285 AL 90	YUCATÁN	SUCURSAL MÉRIDA CALLE 33 #600 Y 602, LOCALIDAD ITZINCAZ Y MULSAY, MPIO. UMÁN, C.P. 97390, MÉRIDA, YUC. TEL.: 999 912 2451
MICHOACÁN	FIX FERRETERÍAS AV. PASEO DE LA REPÚBLICA #3140-A, COL. EX-HACIENDA DE LA HUERTA, C.P. 58050, MORELIA, MICH. TEL.: 443 334 6858		

Code

28268

Model

LIMI-20P

Brand**PRETUL**

Warranty. Duration: 1 year. Coverage: parts, components and workmanship against manufacturing or operating defects, except if used under conditions other than normal; when it was not operated in accordance with the instructive; was altered or repaired by personnel not authorized by TRUPER. To make the warranty valid, present the product, stamped policy or invoice or receipt or voucher, in the establishment where you bought it or in Corregidora 35, Centro, Cuauhtémoc, CDMX, 06060, where you can also purchase parts, components, consumables and accessories. It includes the costs of transportation of the product that derive from its fulfillment of its service network. Phone number 800-018-7873. Made in China. Imported by TRUPER, S.A. de C.V. Parque Industrial 1, Parque Industrial Jilotepec, Jilotepec, Edo. de Méx. C.P. 54257, Phone number 761 782 9100.



Seal of the commercial establishment. Date of delivery:

WWW.TRUPER.COM

10-2023

WWW.TRUPER.COM

Sello del establecimiento comercial. Fecho de entrega:



Garantía. Duración: 1 año. Cobertura: piezas, componentes y mano de obra contra defectos de fabricación ofuncionamiento, excepto si se usó en condiciones distintas a las normales; cuando no fue operado conforme a las instrucciones; fue alterado o reparado por personal no autorizado por TRUPER®. Para hacer efectiva la garantía se presentará el producto, sellada o recibo o comprobante que demuestre lo comprado en Corregidora 35, Centro, Querétaro, CDMX, 06060, donde también podrá adquirir partes, componentes, consumibles y accesorios. Incluye los gastos de transportación del producto que deviven de su cumplimiento o en Corregidora 35, Centro, Querétaro, CDMX, 06060, donde también podrá adquirir partes, componentes, consumibles y accesorios. Precio: 800-018-7873. Made in/Hecho en China. Importador TRUPER, S.A. de C.V. Padrone industrial 1, Parque Industrial Jilotepec, Jilotepec, Edo. de Mex. C.P. 54257, Tel. 761 782 9100. de su red de servicios. Tel. 800-018-7873. Made in/Hecho en China. Importador TRUPER, S.A. de C.V. Padrone industrial 1, Parque Industrial Jilotepec, Jilotepec, Edo. de Mex. C.P. 54257, Tel. 761 782 9100.

Código	Modelo	Marcia	PRTUL	LMI-20P	28268
--------	--------	--------	-------	---------	-------

garantía
Poliza de


PRTUL



En caso de tener algún problema para contactar un Centro de Servicio Autorizado TRUPER, consúltenos en este número donde le informaremos cuál es el centro de servicio más cercano.

D&G China WWW.TRUPER.COM donde obtendrá un listado actualizado, o llame al: 800 690 6990 u 800-018-7873

MICHIGAN FIC FERRETERIAS	MIAMI, TEL.: 443 334 6858 AV. PASEO DE LA REPUBLICA #30-A, COL. ED-HA-KENIA, C.P. 30850, MORELIA, MICH. TEL.: 443 334 6858
JALISCO SUCURSAL GUADALAJARA	TEL.: 33 3606 5285 AL 90 AV. DULCE B. HORN #6800, COL. SANTA CRUZ DEL VALLE, C.P. 45655, TLAJOMULCO DE ZAMORA, JAL.
HIDALGO FERRETEROS S.A DE C.V.	TEL.: 775 753 6615 / 775 753 6616 HGO. TEL.: 775 753 6615 / 775 753 6616 LEADERDAR INDUSTRIAL #34 LOCAL 301C, INTERROR DE PESADE RODRIGUEZ, COL. CENTRO, C.P. 43400, TULANCINGO, HGO. TEL.: 775 753 6615 / 775 753 6616
GUERRERO CENTRO DE SERVICIO ECPSE	CHILPANCINGO, GRO. TEL.: 471 478 5793 CALLE PRINCIPAL MZ. 1, COL. SANTA FE, C.P. 39101,
GUANAJAUTO CLAS. FERRETERIA NUEVO UNICO S.A DE C.V.	CELMAT, GTO. TEL.: 461 671 7578 / 79 / 80 / 88 AV. MEXICO #203, CD. INDUSTRIAL, C.P. 38010,
ESTADOS MEXICO SUCURSAL CENTRO LLOTEPEC	TEL.: 171 781 9101 EXT. 5250 JUJOTEPIC, JUJOTEPIC, ED.O. DE MEZC.F. 54257 PROBLEMA INDUSTRIAL #1, COL. PRÓLOGUE INDUSTRIAL
DURANGO TORNADOS AGUILA, S.A DE C.V.	DCO., TEL.: 618 871 1946 / 618 878 1844 MZAZQUI #200, COL. LUIS ECHEVERRIA DURANGOCO.
COAHUILA SUCURSAL TORRENCON	TEL.: 34 322 1986 / 332 8013 TEPEMIRE, C.P. 28293 MAZATLÁN COAH. BUDV. MIGUEL DE LA MADRID #190, PARQUE INDUSTRIAL
MEXICO FIC FERRETERIAS	TEL.: 8-71 209 08 25 ORIENTE C.P. 2728, TORREON, COAH.
COAHUILA SUCURSAL CHIHUAHUA	TEL.: 55 5522 5051 / 5522 4861 COL. CENTRO, C.P. 66060, CIUDAD METROPOLITANA, CDMX
CHIHUAHUA FIC FERRETERIAS	CHIHUAHUA, CHIH. TEL.: 614 434 0052 BARRERA CENTRAL MEXICO CIUDAD METROPOLITANO, C.P. 31415.
CHIHUAHUA TORNADOS CAMPEHE	TEL.: 8-71 32 1115 TACACHULA, CHIH. TEL.: 962 118 4083 AV. ALVARO OBREGÓN #24, COL. SEPIRANZA C.P. 24800 CAMPECHE, CAMP. TEL.: 981 815 2808
CALIFORNIA SUR SUCURSAL TIJUANA	NEVO, C.P. 26260, CD. CONSULTORIUM, B.C.S.
AGUASCALIENTES DE TODO PARA LA CONSTRUCCION	TEL.: 664 969 5100 FIRDOFI II, C.P. 22244, TIJUANA, B.C.
BAJA SUCURSAL TIJUANA	TEL.: 735 258 8931 CARRETERA INTERNACIONAL #171, COL. CENTRO, C.P. 20050, MAZATLÁN #171, COL. CENTRO, C.P. 63000, TEPIC, NAY.
NAYARIT SUCURSAL MOTORRENT	TEL.: 735 258 8931 CARRETERA INTERNACIONAL #400, 100 MONTERREY PARKS, NUEVO LEÓN, TEL.: 81 8352 8791 / 81 8352 8790 COLONIA PLATA DE NAHUCA, C.P. 66025, ESCOBedo, NUEVO LEÓN, TEL.: 81 8352 8791 / 81 8352 8790
MORELOS FIC FERRETERIAS	TEL.: 735 258 8931 CARPINTERIA ANUZURIES #95, ESQ. JOSE PEREZ, COL. CENTRO, C.P. 62740, CUAUTLA, MORELIA.
NAVARA HERRAMIENTAS DE TEPIC	TEL.: 735 258 8931 CARPINTERIA ANUZURIES #95, ESQ. JOSE PEREZ, COL. CENTRO, C.P. 62740, CUAUTLA, MORELIA.
SAN LUIS FIC FERRETERIAS	TEL.: 664 713 1939 / 173 8400 SAN LUIS POTOSI, SL.P. TEL.: 444 822 4311
QUINTANA ROO FIC FERRETERIAS	TEL.: 664 713 1939 / 173 8400 AV. UNIVERSIDADE SUR #4305, COL. LAS PASOS, C.P. 78320, MORA C.P. 80183, CL. CUMBACAN, SIN.
SINALOA SUCURSAL KOMATEL	TEL.: 664 713 1939 / 173 8400 AV. LAS REYES KM1.5 SUR #4305, COL. HACIENDA DE LA PAZ, SAN LUIS POTOSI, SL.P. TEL.: 444 822 4311
POTOSI FIC FERRETERIAS	TEL.: 664 713 1939 / 173 8400 AV. LAS REYES KM1.5 SUR #4305, COL. HACIENDA DE LA PAZ, SAN LUIS POTOSI, SL.P. TEL.: 444 822 4311
SONORA FIC FERRETERIAS	TEL.: 664 713 1939 / 173 8400 CALLE 5 DE FEBRERO #57, SUR LT. 25 MZ. 10, COL. SANTO DOMINGO, C.P. 80000, CD. OBREGÓN, SON.
TAMAULIPAS FM RINCONES REACCIONES	TEL.: 664 713 2592 CALLE 16 HECHO LOS 1, 2 Y 3 MZ., 1 COL. INDUSTRIAL, ZONA NORTE, TAB.
TJALACLA SERVICIOS Y HERRAMIENTAS INDUSTRIALES	TEL.: 222 271 7502 C.P. 90901, PABLO DEL MONTE TAXCO, PABLO DEL MONTE TAXCO, MEXICO.
VERACRUZ LA CASA DISTRIBUIDORA TRUPER	TEL.: 782 283 8100 / 828 6484 PRIMERAS C.P. 33050, PDMZ R.C.A., VER.
MEXICO SUCURSAL MERIDA	TEL.: 993 99 73 2451 MPD. UMAN, C.P. 97300, MERIDA, YUC.
YUCATAN SUCURSAL MERIDA	TEL.: 993 99 73 2451 MPD. UMAN, C.P. 97300, MERIDA, YUC.



Notas

PRETUL

Los aparatos eléctricos y las baterías no deben desecharse junto con los desperdicios domésticos. Por favor, entregue la desechar a un centro de reciclaje. Véase que la desechar en el basurero.

PROBLEMA DE PROBLEMAS

Problema	Causa	Solución
La batería no se carga y la heramienta no funciona.	<ul style="list-style-type: none"> Batería mal colocada en el cargador. Revisar que la conexión esté segura y bien conectada al tomacorriente. Limpieza de immediato con agua y jabón el líquido de la pileta o ropa. Reemplazar la pila por una nueva de 5 minutos. Detenegá la herramienta por espacio de 5 minutos para que la batería se encienda. 	<ul style="list-style-type: none"> Permitir que la herramienta sea limpia por completo con agua y jabón el líquido de la pileta o ropa. Reemplazar la pila por una nueva de 5 minutos. Detenegá la herramienta por espacio de 5 minutos para que la batería se encienda.
El cargador no apaga y la herramienta no gira.	<ul style="list-style-type: none"> Cargarla en posición de giro a la inversa. Moverla en posición de giro a la inversa. 	<ul style="list-style-type: none"> Apagarla en posición de giro a la inversa. Moverla en posición de giro a la inversa.
La herramienta pierde eficiencia.	<ul style="list-style-type: none"> Cargue la batería. Batería baja. 	<ul style="list-style-type: none"> Cargue la batería. Batería baja.

PRETUL

SOLUCIÓN DE PROBLEMAS

Problema	Causa	Solución
La batería se calienta durante la operación.	<ul style="list-style-type: none"> La batería se calienta durante la operación. Este cargador de duración corta. Este calentamiento es normal. 	<ul style="list-style-type: none"> Retirar la herramienta y permitir que la batería se enfrie. Este calentamiento es normal.
La batería se calienta durante la operación.	<ul style="list-style-type: none"> La batería se calienta durante la operación. Este calentamiento es normal. Este calentamiento es normal. 	<ul style="list-style-type: none"> Retirar la herramienta y permitir que la batería se enfrie. Este calentamiento es normal. Este calentamiento es normal.
La batería gotea.	<ul style="list-style-type: none"> Carga de immedio podría presentarse en la batería gotea. Temperaturas extremas o desbajo de uso normal causan que la batería gotee. Si goteo intensos o muy evidentes es debido a temperatura ambiente. 	<ul style="list-style-type: none"> Dejarla que la herramienta esté seca. Retirar la herramienta y permitir que la batería se enfrie. Retirar la herramienta y permitir que la batería se enfrie.
La batería no se calienta ni funciona.	<ul style="list-style-type: none"> Carga y la luz del cargador no Este cargador de duración corta. Este cargador de duración corta. 	<ul style="list-style-type: none"> Este cargador de duración corta. Este cargador de duración corta. Este cargador de duración corta.

PRETUL

SOLUCIÓN DE PROBLEMAS

- Recomendado:** Puedes poner demasiada tensión sobre los sujetadores o hacer que se rueden o dañen.
- Tiempo de ajuste:** Un tiempo mayor de ajuste aumenta el par de ajuste. Un tiempo de ajuste mayor al que se aprecia.
- Material:** El tipo de material acondicionado de la superficie del material afectará el par de ajuste.
- Peso:** Asegúrate de que todos los lados estén libres de óxido y otros desechos para permitir un par de ajuste.
- La tensión de fijación también varía con el diámetro del tornillo y la configuración de torsión.**
- Tamaño del perno:** Los pernos de mayor diámetro generalmente requieren una mayor tensión de fijación.
- Volante:** El balancín volante por una batadera o placa casillera completa causará una reducción en el par de ajuste.
- Tamaño del accesorio:** El uso de accesorios incorrectos causará una reducción en el par de ajuste.

Considera los siguientes puntos ya que el par de ajuste puede ser afectado por cada uno de ellos:

Ajustar - desatornillar




- Interruptor de encendido/apagado.
- Intermédia para bloquear el movimiento del mecanismo de detención.
- Mueve el botón de dirección de giro a la posición media para mover el interruptor de encendido/apagado.
- Al soltar el interruptor de encendido/apagado, la interrupción, más rápido opera la herramienta.
- El interruptor permite seleccionar la velocidad adecuada para cada tarea. Mientras más apriete el interruptor para detener la operación.
- Presione el interruptor para iniciar la operación.

Encendido y control de operación

- Si nunca va a necesitar el clip, puede extraerlo de la herramienta a ensamblar en otro lado. Asegúrate de tener bien el tornillo.
- Si quiere mover el clip para centrarlo en otro lado, quite el tornillo que sostiene el clip para centrarlo en su lugar y vuelvalo de este modo podrá adaptarse a susurios surcos o desechos.
- El clip para centrarlo puede ser ensamblado a cualquier lado de la herramienta utilizando solo el tornillo provisto.

Clip para centración




- La primera vez que encienda la herramienta en función automática.
- Para no dejar la herramienta encendida la herramienta de rotación de la herramienta se encenderá la dirección de la rotación en la dirección de la rotación.
- Para no presentar ningún problema.
- La primera vez que encienda la herramienta después de mantenerla en rotación, puede sacudirse un "click". Esto es normal y no representa ningún problema.
- La herramienta de rotación de la herramienta de rotación se bloqueará si el botón de dirección es girado hasta la posición de en medio.
- El interruptor de sentido y desatornillar, presione el botón de dirección de la herramienta de rotación.
- Para invertir el sentido de las marcas púntadas hacia la izquierda.
- Para atornillar, use el interruptor y presione el botón de dirección de la herramienta de rotación.

Dirección de rotación

Puesta en marcha


PRETUL



- Con la máquina apagada, coloque el botón de dirección en la posición de bloqueo (al centro).
- Tome el dado y empújelo con firmeza sobre el cuadro. El anillo retenedor se comprenderá que el accesorio se deslice encima. Una vez instalado el accesorio, el anillo retenedor aplicará presión que ayudará a retención del accesorio.

Retirar accesorio

Instalación del dado			
Indicadores de LED			
del cráneo tiene 2	del proceso de carga:	Carácter de la batería en curso	Encendido
que indica el estado	para la indicación de carga.	Apagado	Apagado
Modo de espera: No hay ninguna batería instalada o se ha instalado la batería.	modo de espera	Encendido	Apagado
Y si el LED permanece:	que indica el estado del proceso de carga:	Si en energía	Apagado



- Para instalar la batería en el mango de la herramienta, linne la unidad de batería en la herramienta.
- La batería tiene DESCRAGADA de fabrica. Si es necesario que la cargue por primera vez debe esperar 5 minutos de descarga / recarga para ser recargada. Permita que la batería se caliente demasiado como para ser recargada. En un ambiente caliente o despidiendo uso prolongado, es posible que la temperatura de la batería sea menor al rango óptimo de control electrónico.
- La temperatura normal de la batería es de 0 °C a 45 °C. Fuera de este rango se suspende la carga automáticamente hasta que la temperatura de la batería es de 0 °C a 75 °C. Si los 75 °C se exceden, el alcance de temperatura normal de descarga / recarga es de 0 °C a 55 °C. Una vez que la temperatura de la batería es de 0 °C a 75 °C, la temperatura de la batería se calienta durante el trabajo, la herramienta se calienta más rápidamente y es posible que la batería se dañe.
- Para retirar la batería de la herramienta, presione el botón de liberación (G) en el mango hasta que la batería se libere de la herramienta, presione el botón de liberación en la herramienta, y tire firmemente de la batería para sacarla del mango de la herramienta.

Instalar y retirar la batería

Consideraciones para el uso de la batería


PRETUL

Puesta en marcha

- **ADVERTENCIA** • El uso de accesorios que no sean de sujeción provoca roturas y situaciones de peligro.
- **ADVERTENCIA** • Cuando un dado no ha sido segurado y sujeto como se indica, puede saltar disparando y lesionar al operador.
- Los adaptadores para dados de otras medidas no se recomiendan.
- Utilice dados para cuadro de 1/2" (13 mm).
- Clavos de cuadro cuadros con tallo recto, verifique que el goma y punta de acero a clavarlo en el impulsor de cuadro.
- En caso de que el dado cuadre con otros, siempre utilice anillos utilizados solo si es estrechamente necesario.
- Usar adaptadores para dados de otras medidas no se recomienda.
- Los adaptadores para cuadro cuadrado de 1/2" (13 mm) para concocer nuestra gama de accesorios.
- Siempre utilice dados de cuadro para esta herramienta. No utilice dados para herramientas de mano. Consulte el Catálogo **PRETUL** para conocer nuestra gama de accesorios.
- Para retirar un accesorio, apague la máquina, sujete el accesorio y jalelo firmemente.

Impedimento de la sujeción para garantizar la ausencia de gretas.


Impedimento de la sujeción para garantizar la ausencia de gretas.



- Si la luz roja en el indicador de nivel de batería parpadea, es necesario que la temperatura de la batería sea menor a 0 °C o mayor a 45 °C. Especie a que la temperatura de la batería sea menor a 0 °C o mayor a 45 °C. Si las luces indicadoras de la batería no se encienden después de insertarla en el cargador, sustituya la batería por una nueva.
- Si la luz roja en el indicador de nivel de batería permanece encendida en el cargador durante más de 10 segundos, desconecte el cargador de la corriente una vez concluida la carga.
- Desconecte el cargador de la corriente y lo retire de la red eléctrica.
- Cuando la batería se enciende completamente cargada, la luz verde se encenderá y la luz verde se apagará.
- Inserte la batería en el cargador deslizándola como se muestra en la imagen. La luz verde se apagará si la batería está encendida.
- Una vez que la batería se encienda, el cargador deslizará la batería en la ranura, indicando que la carga se ha iniciado.
- Conecte la clavija del cargador en un tomacorriente de 12 V ~

Carga de la batería

Puesta en marcha



Partes

PRETUL



especiales para el uso en exteriores y reducen el riesgo de sufrir una descarga eléctrica.

ADVERTENCIA Al operar herramientas eléctricas en exteriores, utilice una extensión aterrizada marcada como "uso exterior" marca **VOLTECK**. Estas extensiones son

AWC (calibre de aluminio estandarizado (American Wire Gauge). Referencia: NMX-J-153-ACCE

* Se permite utilizarlo siempre que las extensiones mismas cumplan con un criterio de protección contra sobrecorriente.

de 0 A hasta 10 A	16 AWG(*)	16 AWG	16 AWG	16 AWG	14 AWG	14 AWG	14 AWG	12 AWG	12 AWG	8 AWG	8 AWG	de 15 A hasta 20 A
-------------------	-----------	--------	--------	--------	--------	--------	--------	--------	--------	-------	-------	--------------------


Capacidad en Amperes Número de conductores de 18 m a 15 | mayor de 15 m

Calibre de extensión

herramienta. Si tiene cables use el siguiente calibre más alto.

use este dispositivo de la longitud del cable y de la capacidad de amperaje indicada en la placa de datos de la herramienta perdida de potencia y sobreeléctricos del motor. La siguiente tabla muestra los datos que deben resultar de acuerdo con el consumo de energía que se requiere para transportar la corriente que se consume en la herramienta. Un cable inferior o de menor calidad que la especificada en la línea, tiene tendencia a causar daños en el cable de extensión, así como a disminuir la eficiencia del mismo.

ADVERTENCIA Al usar un cable de extensión, asegúrese de usar el calibre suficiente para transportar la corriente



con conexión a tierra a través de un sistema de conexión eléctrica con conexión a tierra. Ambos tipos de sistemas eliminan la necesidad de un cable de conexión de tres cables不平衡 (imbalanced) que tiene un conductor neutral polarizado. No utilice el clavija en forma alguna. El dispositivo de protección debe ser usado en el enchufe, solamente. Si aun así no es posible, pongase en contacto con un electricista localizado o instale un dispositivo polarizado. Si la clavija no es de una forma. Si la clavija es de una forma polarizada (una pata es más ancha que la otra). Esta herramienta es de doble aislamiento y aislamiento rotulado.

ADVERTENCIA Las herramientas de doble aislamiento solo pueden conectarse de una forma. Esto

Reduquerimientos eléctricos



ADVERTENCIA Antes de obtener acceso a las terminales, todos los circuitos de alimentación deben ser desconectados. de líquidos durante su operación. No lo exponga a la lluvia, líquidos y/o humedad.



La construcción del aislamiento eléctrico de esta herramienta es similar a las aplicaciones de raramentado. Centro de Servicio Autorizado TRUPER, con el fin de evitar algún riesgo de descarga o accidente considerable.

ADVERTENCIA Si el cable de aislamiento de daria, este debe ser reemplazado por el fabricante o un centro de servicio autorizado. No lo exponga a la lluvia, líquidos y/o humedad.

La clase de construcción del cargador es: Aislamiento reforzado

El cable de alimentación tiene sujetacables tipo: Y La clase de construcción de la herramienta es: Clase III

Carga • Entrada: Tension: 127 V ~	Tiempo de carga: 20 minutos aproximadamente	Corriente de entrada: 0.9 A
Batería • Ión-litio 20 V = 4 Ah	Entrada: Tension: 09 Hz	Frecuencia: 60 Hz
Torque máximo • 155 lb·ft (210 Nm)	Entrada: Tension: 127 V ~	Salida: 21 V = 2.5 A
Grado IP • IP 20	Entrada: Tension: 127 V ~	Entrada: Tension: 127 V ~
Rotación • adelante - reversa	Entrada: Tension: 127 V ~	Entrada: Tension: 127 V ~
Golpes por minuto • 0 golpes/min - 3 000 golpes/min (BPM)	Entrada: Tension: 127 V ~	Entrada: Tension: 127 V ~
Velocidad • 0 r/min - 2 200 r/min (RPM)	Entrada: Tension: 127 V ~	Entrada: Tension: 127 V ~
Tensión • 20 V =	Entrada: Tension: 127 V ~	Entrada: Tension: 127 V ~
Cuadro • 1/2" (13 mm)	Entrada: Tension: 127 V ~	Entrada: Tension: 127 V ~
Descripción • Llave de impacto italiana	Entrada: Tension: 127 V ~	Entrada: Tension: 127 V ~
Código • 28268	Entrada: Tension: 127 V ~	Entrada: Tension: 127 V ~

LIMI-20P

RECOMENDACIONES DE USO Y CUIDADOS

A ATENCIÓN

Para poder sacar el máximo provecho de la heramienta, alargar su vida útil, hacerla más resistente y evitar riesgos o lesiones graves, es fundamental leer este instructivo por completo antes de usar la herramienta.

Guarde este instructivo para futuras referencias.


Los artículos de este instructivo son para referencia, pueden variar del artículo real de la herramienta.

- | | |
|-----------|---|
| 12 | Policía de garantía |
| 11 | Centros de servicio autorizados |
| 10 | Notas |
| 9 | Protección ambiental |
| 6 | Mantenimiento |
| 6 | Solución de problemas |
| 6 | Puesta en marcha |
| 5 | Partes |
| 4 | Llave de impacto intercambiable |
| 3 | Advertencias de seguridad para uso de herramientas eléctricas |
| 3 | Requerimientos técnicos |



Lea este instructivo por completo
antes de usar la herramienta.

! ATENCIÓN



LIMI-20P

28268 LIMI-20P

Código Modelo

Este instructivo es para:

20V = 1/2"
13 mm Cuadro

Llave de impacto inalámbrica

Instructivo de

PRETUL®

ESPAÑOL
ENGLISH